Asbestos License #73261---Asbestos Certification # 92-09664

P.O. Box 188 Pulaski, New York 13142 (315)527-8888

ASBESTOS BUILDING INSPECTION REPORT PRE-DEMOLITION BUILDING SURVEY

PERFORI	MED FOR:
Greater Mohawk Valley	Land Bank
500 East Main Street - S	Suite 2A
Little Falls	
PROJE	CT SITE: y Land Bank
46 Division Street	
Fort Plains	, New York
0 4	1 5 1 9



P.O. Box 188 Pulaski, New York 13142 (315)527-8888

CONTENTS

1.0	EXECUT	IVE SUMMARY ————————————————————————————————————	. 1				
2.0	INTROD	INTRODUCTION					
3.0	BACKGF	ROUND	.1				
4.0	METHO	OOLOGY	2				
5.0	SUMMAI	RY OF FINDINGS	3				
6.0	RESPONSIBILITY OF OWNER OR OWNERS AGENT						
7.0	ASBESTOS CONTROL BUREAU DISTRICT OFFICES						
		rials analyzed and found to be ACM estos Bulk Sample Summary	5				
Apper	ndices						
,	ndix A	Certifications and License					
Appe	ndix B	Floor Plan Drawings and Pictures					
Appe	ndix C	Laboratory Analysis Reports and Chain of Cus	stody				
Appei	ndix D	Laboratory License and Certificates					

Asbestos License #73261—Asbestos Certification # 92-09664

P.O. Box 188 Pulaski, New York 13142 (315)527-8888

1.0 EXECUTIVE SUMMARY

A2Z Environmental IIc. was retained by Greater Mohawk Valley Land Bank to perform a limited pre-demolition building survey for asbestos containing materials (ACM). This is report is not to be used for design purposes. Measurements are for a guide and should be verified by abatement contractor. There may be areas that were inaccessible for the inspector to sample.
The survey was performed by <u>Jamie Foster (92-09964)</u> , New York State certified building inspector (certificate Number 92-09664) for A2Z Environmental IIc. and included the following:
Review of available building records for reference to ACM; Visual inspection of the area to identify suspect ACM; Collection of representative samples of suspect ACM; Analysis of all samples by an independent, accredited laboratory; Preparation of a written report.
Fieldwork for the survey was performed on $04-05-2019$. Samples were delivered to EMSL Analytical INC. for polarized light microscopy (PLM) or (TEM) analysis on $04-06-2019$. The survey included the collection and analysis of 30 samples.
2.0 INTRODUCTION
The survey was performed at the request of John Mazzarella III in preparation for possible located at 46 Division Street The objective of the survey was to identify ACM within the space or the entire building so that appropriate considerations can be made prior to demolition of the building or renovation of the said space.
New York State Department of Labor Industrial Code Rule 56 (12NYCRR, Part 56) requires that prior to advertising for bids or contracting for or commencing work on any demolition work on a building, that the owner or agent of such building shall cause a survey for ACM to be conducted, and that identified ACM be removed by a licensed contractor prior to initiation of demolition activities. This survey was performed in accordance with these requirements.

3.0 BACKGROUND

There are many factors that must be considered when determining the extent of potential health risks associated with the presence of asbestos-containing materials (ACM) in buildings. The major concern is with the possibility of fiber release from the ACM and the subsequent inhalation of these fibers by building occupants.

P.O. Box 188 Pulaski, New York 13142

(315)527-8888

Asbestos is a known carcinogen found in many types of building materials, but its presence alone may not constitute a health hazard. Rather, a health hazard occurs when the asbestos fibers are in some way disturbed and become airborne. Asbestos fibers are most likely to be released into the air when the materials in which they are contained become loose, friable, or otherwise show signs of damage or deterioration by various causal agents.

Inhalation of these microscopic asbestos fibers has been medically proven to cause chronic disease such as asbestosis, mesothelioma and lung cancer. The severity of these diseases, along with the discovery of great amounts of asbestos in public and private buildings, has led government agencies to promulgate regulations aimed at reducing asbestos exposure. Maximum allowable exposure levels have been set for building occupants, and methods of compliance for removal and disposal of ACM have been instituted. Therefore, it is necessary to locate and identify all ACM within a building. Comprehensive data to this effect will allow for the implementation of a systematic asbestos abatement program.

4.0 METHODOLOGY

The bulk sampling procedure utilized by A2Z Environmental LLC. is designed to collect samples of materials suspected to contain asbestos. Each individual type of materials as delineated by color, texture, pattern and location will be referred to as a homogeneous sampling area. Each homogeneous area will be sampled and assessed independently of each other.

The procedure for collecting a bulk sample entails complete penetration and removal of all layers of the suspect material, while at the same time, minimizing damage and potential fiber release. The sampling procedure begins with complete wetting of the sampling area. A core section is then cut from the material and placed in a sealed, airtight sample container. The exposed area is then sealed with spray adhesive and patched with duct tape when in an occupied space. The area where the core sample was removed is then labeled with a sample number to facilitate future reference. The sampling tool is then wet wiped and decontaminated with a disposable towel.

Each labeled sample is then transported along with a chain of custody form to a certified laboratory for analysis. Laboratory analysis of friable samples (materials which are able to be crushed or reduced to powder by hand pressure) is performed using Polarized Light Microscopy with Dispersion Staining in accordance with the EPA Interim Method for the Determination of Asbestos in Bulk Insulation Samples (EPA - 600/M4-82-020).



P.O. Box 188 Pulaski, New York 13142 (315)527-8888

Non-friable organically bound samples (NOBs) such as floor tile and roofing undergo gravimetric reduction and are then analyzed using (PLM) polarized light microscopy. Samples that test positive for asbestos are reported as such. Samples which test negative for asbestos (less than 1 % asbestos by weight) must be further analyzed by (TEM) transmission electron microscopy.

The testing laboratory is approved under the NYS Department of Health - Environmental Laboratory Approval Program (ELAP) as well as the National Institute of Standards and Technology - National Voluntary Laboratory Approval Program (NVLAP).

SUMMARY OF FINDINGS 5.0

There were no	building re	ecords ava	ilable at the	e time o	of the survey	, therefore	building
records have 🗵	have not,	been revie	ewed as par	t of this	effort.		
The laboratory visi	ually insne	cted for t	he nresenc	e of su	ispect ACM	on	

04-08-2019&04-12-2019

See Table 5.1 (starting on page 5) for a complete list of samples collected. If any additional suspect materials are discovered prior to or during demolition activities, then the material must be assumed to be asbestos-containing or must undergo Laboratory analysis in accordance with 29 CFR 191 0.1 1 01 to prove it non-asbestos.

** SEE APPENDIX B FOR LOCATIONS OF ACM **

It must be noted that the quantities of ACM provided on table 5.1 are estimates of the actual materials present that were available for inspection and assessment. These figures themselves should not be used as the sole basis for asbestos abatement contractors' bids or cost estimates. They are meant merely as estimates to gauge the scope of the project.

The purpose of the inspection was to determine the extent of asbestos-containing materials associated with the above referenced property only. New York State Department of Labor Regulations, 12 NYCRR Part 56, requires removal of all asbestos-containing materials from a building or structure prior to demolition or renovation activities.

Details concerning ACM location and quantity, sample locations, laboratory analysis, and consultant credentials are included in this report.

Responsibility of owner or owner agent 6.0

The owner or owners agent is required to send a copy of this report to the Department of Labor prior to any Asbestos Abatement. The address that the report needs to be sent to depends on the county that the property is located. The addresses for the different Department of Labor District offices are listed on page 4 of this report.

ASBESTOS TESTING

Asbestos License #73261---Asbestos Certification # 92-09664

P.O. Box 188 Pulaski, New York 13142 (315)527-8888

7.0 ASBESTOS CONTROL BUREAU DISTRICT OFFICES

ALBANY DISTRICT:

Counties - Albany, Clinton, Columbia, Dutchess, Essex, Fulton, Green, Montgomery, Orange, Putnam, Rockland, Rensselaer, Saratoga, Schenectady, Schoharie, Sullivan, Ulster, Warren, Washington

State Office Campus, Room 157, Albany, NY 12240 (518) 457-1255 (FAX) (518) 485-8054 (Field Office)

BUFFALO DISTRICT:

Counties - Cattaraugus, Chautauqua, Erie, Genesee, Livingston, Monroe, Niagara, Ontario, Orleans, Wayne, Wyoming, Yates

65 Court Street, Rm. 405, Buffalo, NY 14202 (716) 847-7601 (716) 847-7126 (FAX) (716) 847-7138

NEW YORK CITY DISTRICT:

Counties - Bronx, Kings, Nassau, New York, Queens, Richmond, Suffolk, Westchester

One Hudson Square, 75 Varick Street (7th Floor), New York, NY 10013 (212) 775-3532

SYRACUSE DISTRICT:

Counties - Allegany, Broome, Cayuga, Chemung, Chenango, Cortland, Delaware, Franklin, Hamilton, Herkimer, Jefferson, Lewis, Madison, Oneida, Onondaga, Oswego, Otsego, St. Lawrence, Schuyler, Seneca, Steuben, Tioga, Tompkins,

450 S. Salina Street, Syracuse, NY 13202 (315) 479-3215 (FAX) (315) 479-3333

Asbestos License #73261---Asbestos Certification # 92-09664

P.O. Box 188 Pulaski, New York 13142 (315)527-8888

All remaining suspect ACM were analyzed at an independent, accredited laboratory. Table 5.1 summarizes the bulk sampling analytical results.

Table 5.1 - Asbestos Bulk Sample Summary of asbestos containing materials

Sample Number	Material Sampled	Condition	Lab Results (% Asbestos)	Estimated Quantity
19-9a	aluminum roof coat - front porch roof	damaged	9.70% Chrysotile	160 sq'
20-9b	aluminum roof coat - front porch roof	same as 19-9a	same as 19-9a	same as 19-9a
21-10a	aluminum roof coat - main roof - bottom layer	good	9.20% Chrysotile	1100 sq'
22-10b	aluminum roof coat - main roof - bottom layer	same as 21-10a	same as 21-10a	same as 21-10a
M. 4				
				
Marie especial control of the contro				
			1	

Laboratory reports are included as Appendix C to this report. Floor plan drawings identifying sample locations and locations of identified ACM are included as Appendix "B"

Ashestos License #73261---Asbestos Certification # 92-09664

P.O. Box 188 Pulaski, New York 13142 (315)527-8888

Appendix A

Certification and License

New York State - Department of Labor

Division of Safety and Health License and Certificate Unit State Campus, Building 12 Albany, NY 12240

ASBESTOS HANDLING LICENSE

A 2 Z Environmental LLC

P.O. Box 188

Pulaski, NY 13142

FILE NUMBER: 13-73261 LICENSE NUMBER: 73261

LICENSE CLASS: RESTRICTED DATE OF ISSUE: 10/10/2018 EXPIRATION DATE: 10/31/2019

Duly Authorized Representative - Jamie D Foster.

This license has been issued in accordance with applicable provisions of Article 30 of the Labor Law of New York State and of the New York State Codes, Rules and Regulations (12 NYCRR Part 56). It is subject to suspension or revocation for a (1) serious violation of state, federal or local laws with regard to the conduct of an asbestos project, or (2) demonstrated lack of responsibility in the conduct of any job involving asbestos or asbestos material.

This license is valid only for the contractor named above and this license or a photocopy must be prominently displayed at the asbestos project worksite. This license verifies that all persons employed by the licensee on an asbestos project in New York State have been issued an Asbestos Certificate, appropriate for the type of work they perform, by the New York State Department of Labor.

File of Thanks

Eileen M. Franko, Director For the Commissioner of Labor

SH 432 (8/12)

STATE OF NEW YORK - DEPARTMENT OF LABOR
ASBESTOS CERTIFICATE

JAMIE D FOSTER
CLASS(EXPIRES)
C ATEC(10/19) D INSP(10/19)
H PM (10/19) I PD (10/19)

CERT# 92-09664 DMV# 611729837

MUST BE CARRIED ON ASBESTOS PROJECTS


Ashestos License #73261---Ashestos Certification # 92-09664

P.O. Box 188 Pulaski, New York 13142 (315)527-8888

Appendix B

Floor Plan Drawings and Pictures







Asbestos License #73261---Asbestos Certification # 92-09664

P.O. Box 188 Pulaski, New York 13142 (315)527-8888

Appendix C

Laboratory Analysis Reports and Chain of Custody



EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018
Tel/Fax: (212) 290-0051 / (212) 290-0058
http://www.EMSL.com / manhattanlab@emsl.com

EMSL Order: 031907563 Customer ID: AZCC25

Customer ID: AZC

Project ID:

Attention: Jamie Foster

A2Z Environmental LLC.

PO Box 188

Pulaski, NY 13142

Analyzed

Phone: (315) 527-8888

Fax: (315) 363-4525

Received Date: 04/06/2019 11:44 AM

Analysis Date: 04/08/2019 - 04/12/2019

Collected Date: 04/05/2019

Project: A2Z04052019A/ 46 DIVISION STREET, FORT PLAINS

Test Report: Asbestos Analysis of Bulk Material

Non-Asbestos

Te	est	Analyzed Date	Color		Fibrous	Non-Fibrous	Asbestos
ample ID	01-1A		Description	on	2ND FLOOR FRON	T LEFT BEDROOM - JOINT COMPOUND AND D	PRYWALL
3	031907563-00	001	Homogen	eity	Homogeneous		
PLM NYS 19	98.1 Friable	04/12/2019	Brown/ Gray/ White		6 Cellulose 6 Glass	20.00% Ca Carbonate 50.00% Gypsum 20.00% Non-fibrous (other)	None Detected
LM NYS 19	98.6 VCM						Not Analyzed
LM NYS 19	98.6 NOB						Not Analyzed
EM NYS 19	98.4 NOB		A C 10 A A A A A A A A A A A A A A A A A A	<u></u>			Not Analyzed
Sample ID	02-1B		Descripti	on	2ND FLOOR BACK	RIGHT BEDROOM - JOINT COMPOUND AND D	DRYWALL
	031907563-00	002	Homoger	elty	Homogeneous		
PLM NYS 19	98.1 Friable	04/12/2019	Brown/ Gray/ White		% Cellulose % Glass	25.00% Ca Carbonate 50.00% Gypsum 2.00% Mica 14.00% Non-fibrous (other)	None Detected
PLM NYS 1	98.6 VCM						Not Analyzed
PLM NYS 1	98.6 NOB						Not Analyzed
EM NYS 1							Not Analyzed
Sample ID	03-1C	Mariania Ma	Descripti	on	2ND FLOOR FROM	T RIGHT BEDROOM - JOINT COMPOUND AND	DRYWALL
•	031907563-0	003	Homoger	neity	Homogeneous		
PLM NYS 1	98.1 Friable	04/12/2019	Brown/ Gray/ White		% Cellulose % Glass	40.00% Ca Carbonate 40.00% Gypsum 8.00% Non-fibrous (other)	None Detected
PLM NYS 1	98.6 VCM				Managed and the second		Not Analyzed
PLM NYS 1	98.6 NOB						Not Analyzed
TEM NYS 1					A. Jakes		Not Analyzed
Sample ID	04-2A		Descript	on	ATTIC - INSULATION	ON VAPOR BARRIER	
•	031907563-0	004	Homoge	neity	Heterogeneous		
PLM NYS 1	98.1 Friable						Not Analyzed
PLM NYS 1	98.6 VCM						Not Analyzed
PLM NYS 1	98.6 NOB						Not Analyzed
TEM NYS 1	98.4 NOB	04/08/2019	Brown	******		100.00% Other	None Detected
Sample ID	05-2B		Descript	lon	ATTIC - INSULATION	ON VAPOR BARRIÈR	
307871	031907563-0	0005	Homoge	neity	Heterogeneous		
PLM NYS 1	98.1 Friable						Not Analyzed
PLM NYS 1	198.6 VCM		11			1	Not Analyzed
PLM NYS 1	198.6 NOB						Not Analyzed
TEM NYS 1	198.4 NOB	04/08/2019	Brown			100.00% Other	None Detected



Customer PO: Project ID:

Test Report:Asbestos Analysis of Bulk Material

Non-Asbestos

		Analyzed				Non-Asbestos	
Те	est	Date	Color		Fibrous	Non-Fibrous	Asbestos
Sample ID	06-3A-Linoleun		Description	on	2ND FLOOR BATH	ROOM FLOOR - LINOLEUM WITH MASTIC	
	031907563-0006		Homogen	eity	Heterogeneous		
PLM NYS 19	8.1 Friable				ALL PROPERTY OF THE PROPERTY O		Not Analyzed
PLM NYS 19	98.6 VCM						Not Analyzed
PLM NYS 19	98.6 NOB						Not Analyzed
TEM NYS 19	98,4 NOB	04/08/2019	Beige			100.00% Other	None Detected
Sample ID	06-3A-Mastic		Description	on	2ND FLOOR BATH	ROOM FLOOR - LINOLEUM WITH MASTIC	
	031907563-0006	6A	Homogen	eity	Heterogeneous		
PLM NYS 19	98,1 Friable						Not Analyzed
PLM NYS 19	98.6 VCM						Not Analyzed
PLM NYS 19	98.6 NOB						Not Analyzed
TEM NYS 19	98.4 NOB	04/08/2019	Yellow			100.00% Other	None Detected
Sample ID	07-3B-Linoleur	n	Description	on	2ND FLOOR BATH	ROOM FLOOR - LINOLEUM WITH MASTIC	
	031907563-0007	,	Homogen	eity	Heterogeneous		
PLM NYS 19	98.1 Friable						Not Analyzed
PLM NYS 19	98.6 VCM						Not Analyzed
PLM NYS 19	98.6 NOB						Not Analyzed
TEM NYS 19	98.4 NOB	04/08/2019	Beige			100.00% Other	None Detected
Sample ID	07-3B-Mastic		Description	on	2ND FLOOR BATH	ROOM FLOOR - LINOLEUM WITH MASTIC	
	031907563-0007	7A	Homogen	eity	Heterogeneous		
PLM NYS 19	98.1 Friable						Not Analyzed
PLM NYS 19	98.6 VCM						Not Analyzed
PLM NYS 19	98.6 NOB						Not Analyzed
TEM NYS 19	98.4 NOB	04/08/2019	Yellow			100.00% Other	None Detected
Sample ID	08-4A		Description	on	1ST FLOOR KITCH	IEN - JOINT COMPOUND AND DRYWALL	
	031907563-0008	3	Homogen	eity	Homogeneous		
PLM NYS 1	98.1 Friable	04/12/2019	Brown/ Gray/		Cellulose	20.00% Ca Carbonate	None Detected
			White	4.00%	Glass	55.00% Gypsum 11.00% Non-fibrous (other)	
PLM NYS 1	98.6 VCM						Not Analyzed
PLM NYS 1							Not Analyzed
TEM NYS 1		Name of the latest states and the latest states are the latest states and the latest states and the latest states are the latest states and the latest states are the latest states and the latest states are the latest states and the latest sta			and the second s		Not Analyzed
Sample ID	09-4B		Description	on	1ST FLOOR SIDE I	LIVING ROOM - JOINT COMPOUND AND DRY	
cample in	031907563-0009	9	Homogen		Homogeneous		essecution (Edv
PLM NYS 19		04/12/2019	Brown/ Gray/		Cellulose	15.00% Ca Carbonate	None Detected
		- Ir imited to	White		Glass	55.00% Gypsum	
						18.00% Non-fibrous (other)	Nat A td
PLM NYS 1	98.6 VCM						Not Analyzed
PLM NYS 1	98.6 NOB						Not Analyzed
TEM NYS 1	98.4 NOB						Not Analyzed



Customer PO: Project ID:

Test Report:Asbestos Analysis of Bulk Material

Non-Asbestos

	Amelyman		Non-	Asbestos	
Test	Analyzed Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 10-4C		Description	1ST FLOOR BATHROOM	- JOINT COMPOUND AND DRYWALL	
031907563	-0010	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	04/12/2019		% Cellulose % Glass	35.00% Ca Carbonate 40.00% Gypsum 13.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM			4		Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB			the state of the s		Not Analyzed
Sample ID 11-5A-Flo	or Tile	Description	1ST FLOOR KITCHEN FI	OOR - 12" X 12" SELF STICK TILE	
031907563	-0011	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	04/08/2019	Black		100.00% Other	None Detected
Sample ID 11-5A-Ma	stic	Description	1ST FLOOR KITCHEN F	OOR - 12" X 12" SELF STICK TILE	
031907563	3-0011A	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable	•			TO ADDITION ON BY WORKERS -	Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	04/08/2019	Yellow		100.00% Other	None Detected
Sample ID 12-5B-Fig	oor Tile	Description	1ST FLOOR KITCHEN F	LOOR - 12" X 12" SELF STICK TILE	
03190756	3-0012	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable)	175607			Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	04/08/2019	Black		100.00% Other	None Detected
Sample ID 12-5B-Ma	astic	Description	1ST FLOOR KITCHEN F	LOOR - 12" X 12" SELF STICK TILE	
03190756	3-0012A	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable	•		And the second s		Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	04/08/2019	Yellow		100.00% Other	None Detected
Sample ID 13-6A		Description	1ST FLOOR SIDE LIVIN	G ROOM - INSULATION VAPOR BARRIER	
03190756	3-0013	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable	9				Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	04/08/2019	Brown		100.00% Other	None Detected



Customer PO: Project ID:

Test Report:Asbestos Analysis of Bulk Material

Non-Asbestos

Tes	Analyzed	Color	Fibrous	Non-Fibrous	Asbestos
ample ID	14-6B	Description	1ST FLOOR SIDE LIV	ING ROOM - INSULATION VAPOR BARR	IER
	031907563-0014	Homogeneity	Heterogeneous		
LM NYS 198	3.1 Friable				Not Analyzed
PLM NYS 198	B.6 VCM		AND THE PERSON OF THE PERSON O		Not Analyzed
PLM NYS 198	B.6 NOB		The state of the s		Not Analyzed
TEM NYS 19	8.4 NOB 04/08/201	19 Brown	Andrew Control of the State of	100.00% Other	None Detected
Sample ID	15-7A	Description	BASEMENT RIM BOA	ARD - INSULATION VAPOR BARRIER	
	031907563-0015	Homogeneity	Heterogeneous		
PLM NYS 19	8.1 Friable				Not Analyzed
PLM NYS 19	8.6 VCM		1		Not Analyzed
PLM NYS 19	8.6 NOB	The second secon			Not Analyzed
TEM NYS 19	8.4 NOB 04/08/20 ⁻	19 Brown		100.00% Other	None Detected
Sample ID	16-7B	Description	BASEMENT RIM BOA	ARD - INSULATION VAPOR BARRIER	
	031907563-0016	Homogeneity	Heterogeneous		
PLM NYS 19	8.1 Friable				Not Analyzed
PLM NYS 19	8.6 VCM				Not Analyzed
PLM NYS 19	8.6 NOB				Not Analyzed
TEM NYS 19	8.4 NOB 04/08/20	19 Brown		100.00% Other	None Detected
Sample ID	17-8A	Description	1ST FLOOR FRONT	LIVING ROOM FLOOR - 12" X 12" SELF S	STICK TILE
	031907563-0017	Homogeneity	Heterogeneous		
PLM NYS 19	8.1 Friable				Not Analyzed
PLM NYS 19	8.6 VCM				Not Analyzed
PLM NYS 19	8.6 NOB				Not Analyzed
TEM NYS 19	8.4 NOB 04/08/20	19 Brown		100.00% Other	None Detected
Sample ID	18-8B	Description	1ST FLOOR FRONT	LIVING ROOM FLOOR - 12" X 12" SELF S	STICK TILE
	031907563-0018	Homogeneity	Heterogeneous		
PLM NYS 19	8.1 Friable				Not Analyzed
PLM NYS 19	8.6 VCM				Not Analyzed
PLM NYS 19	8.6 NOB				Not Analyzed
TEM NYS 19	8.4 NOB 04/08/20	19 Brown		100.00% Other	None Detected
Sample ID	19-9A	Description	FRONT PORCH ROC	OF - ALUMINUM ROOF COAT	*
www.wia-wayada-andahadada	031907563-0019	Homogeneity	Heterogeneous		
PLM NYS 19	8.1 Friable				Not Analyzed
PLM NYS 19	8.6 VCM			and the second s	Not Analyzed
PLM NYS 19	8.6 NOB				Not Analyzed
TEM NYS 19	8.4 NOB 04/08/20	19 Black	None	90.30% Other	9.70% Chrysotile



Customer PO: Project ID:

Test Report:Asbestos Analysis of Bulk Material

		Amelywad				
Te	est	Analyzed Date	Color	Fibrous	Non-Fibrous	Asbestos
ample ID	20-9B		Description	FRONT PORCH RO	OF - ALUMINUM ROOF COAT	
	031907563-00	020	Homogeneity			8
LM NYS 19	98.1 Friable					Not Analyzed
PLM NYS 19	98.6 VCM	entered as a supplemental to the desired to the second				Not Analyzed
PLM NYS 19	98.6 NOB			A CONTRACTOR OF THE PARTY OF TH		Not Analyzed
TEM NYS 19	98.4 NOB	04/08/2019	Company of the Compan	and the same of th		Positive Stop (Not Analyzed)
Sample ID	21-10A		Description	MAIN ROOF BOTTO	M LAYER - ALUMINUM ROOF COAT AND TAR	
	031907563-00	021	Homogeneity	Heterogeneous		
PLM NYS 19	98.1 Friable					Not Analyzed
PLM NYS 19	98.6 VCM					Not Analyzed
PLM NYS 19	98.6 NOB					Not Analyzed
TEM NYS 19	98.4 NOB	04/08/2019	Black	None	90.80% Other	9.20% Chrysotile
Sample ID	22-10B		Description	MAIN ROOF BOTTO	M LAYER - ALUMINUM ROOF COAT AND TAR	
	031907563-00	022	Homogeneity			
PLM NYS 1	98.1 Friable	26 19 204050022				Not Analyzed
PLM NYS 1	98.6 VCM					Not Analyzed
PLM NYS 1	98.6 NOB					Not Analyzed
TEM NYS 1	98.4 NOB	04/08/2019				Positive Stop (Not Analyzed)
Sample ID	23-11A		Description	MAIN ROOF TOP LA	AYER - ROLLED ROOFING	
	031907563-00	023	Homogeneity	Heterogeneous		and the second s
PLM NYS 1	98.1 Friable					Not Analyzed
PLM NYS 1	98.6 VCM	V 20 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			"	Not Analyzed
PLM NYS 1	98.6 NOB					Not Analyzed
TEM NYS 1	98.4 NOB	04/08/2019	Black		100.00% Other	None Detected
Sample ID	24-11B		Description	MAIN ROOF TOP LA	AYER - ROLLED ROOFING	
	031907563-00	024	Homogeneity	Heterogeneous		
PLM NYS 1	98.1 Friable	W 1000				Not Analyzed
PLM NYS 1	98.6 VCM					Not Analyzed
PLM NYS 1	98.6 NOB					Not Analyzed
TEM NYS 1	98.4 NOB	04/08/2019	Black		100.00% Other	None Detected
Sample ID	25-12A		Description	SIDE PORCH ROOF	- ASPHALT SHINGLES AND TAR	
	031907563-00	025	Homogeneity	Heterogeneous		
PLM NYS 1	98.1 Friable					Not Analyzed
PLM NYS 1	98.6 VCM				Security (1997)	Not Analyzed
PLM NYS 1	98.6 NOB					Not Analyzed
TEM NYS 1	98.4 NOB	04/08/2019	Black	None	97.10% Other	2.90% Chrysotile



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Material

Non-Asbestos

		Analyzed				
Te	est	Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID	26-12B		Description	SIDE PORCH ROOF	- ASPHALT SHINGLES AND TAR	
	031907563-00	26	Homogeneity			
PLM NYS 19	98.1 Friable					Not Analyzed
PLM NYS 19	98.6 VCM					Not Analyzed
PLM NYS 19	98.6 NOB					Not Analyzed
TEM NYS 19	98.4 NOB	04/08/2019		Andrew Control of the		Positive Stop (Not Analyzed)



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Material

The samples in this report were submitted to EMSL for analysis by Asbestos Analysis of Bulk Materials via NYS ELAP Approved Methods . The reference number for these samples is the EMSL Order ID above. Please use this reference number when calling about these samples.

Report Comments:

Sample Receipt Date: 4/6/2019

Analysis Completed Date: 4/12/2019

Sample Receipt Time: 11:44 AM

Analysis Completed Time: 12:47 AM

Analyst(s):

Ghaly Hemaya PLM NYS 198.1 Friable (2)

Tiquasha Thompson PLM NYS 198.1 Friable (4)

Hongyan Ran TEM NYS 198.4 NOB (21)

Samples reviewed and approved by:

James Hall, Laboratory Manager or Other Approved Signatory

Some PALO

NOB = Non Friable Organically Bound N/A = Not Applicable VCM = Vermiculite Containing Material

-In New York State, TEM is currently the only method that can be used to determine if NOB materials can be considered or treated as non -asbestos containing. All samples examined for the presence of vermiculite when analyzed via NYS 198.1.

-NYS Guidelines for Vermiculite containing samples are available at http://www.wadsworth.org/labcert/elapcert/forms/VermiculiteInterimGuidance_Rev070913.pdf EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations . Interpretation and use of test results are the responsibility of the client. Samples were received in good condition unless otherwise noted.

This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government . This report may contain data that is not covered by the NVLAP accreditation.

Samples analyzed by EMSL Analytical, Inc. New York, NY NYS ELAP 11506

OrderID: 031907563

A2Z Environmental IIc.

P.O. Box 188 Pulaski, New York 13142 (315)527-8888

Chain of Custody Form

Location:	46 Division Street, Fort Plains				
Number:	A2Z04052019a	Page:	1	of	2

Sample #	material sampled	Location	F/NF/NOB	Analysis requested
01-1a	joint compound and drywall	2nd floor - front left bedroom	f Off	plm sample as one
)2-1b	joint compound and drywall	2nd floor - back right bedroom	f	plm sample as one
)3-1c	joint compound and drywall	2nd floor - front right bedroom	f	plm sample as one
)4-2a	insulation vapor barrier	attic	nob	tem HR
)5-2b	insulation vapor barrier	attic	nob	tem
)6-3a	linoleum with mastic	2nd floor - bathroom - floor	nob	tem
)7-3b	linoleum with mastic	2nd floor - bathroom - floor	nob	tem
08-4a	joint compound and drywall	1st floor - kitchen	f	plm sample as one
)9-4b	joint compound and drywall	1st floor - side living room	f	plm sample as one
10-4c	joint compound and drywall	1st floor - bathroom	f	plm sample as one
l 1-5a	12" x 12" self stick tile	1st floor - kitchen - floor	nob ·	tem (**)
12-5b	12" x 12" self stick tile	1st floor - kitchen - floor	nob	tem
13-6a	insulation vapor barrier	1st floor - side living room	nob	tem CO
14-6b	insulation vapor barrier	1st floor - side living room	nob	tem
15-7a	insulation vapor barrier	basement - rim board	nob	tem
16-7b	insulation vapor barrier	basement - rim board	nob	tēm
17-8a	12" x 12" self stick tile	1st floor - front living room - floor	nob	tem
18-8b	12" x 12" self stick tile	1st floor - front living room - floor	nob	tem
19-9a	aluminum roof coat	front porch roof	nob	tem
20-9b	aluminum roof coat	front porch roof	nob	tem

	1	1	
12" x 12" self stick tile	1st floor - front living room	m - floor nob	tem
aluminum roof coat	front porch roof	nob	tem
aluminum roof coat	front porch roof	nob	tem
Instructions: 5 day turn (number and letters indicate m copy of results to a2zconstruct First number is sample number in the copy of the state of the copy of	ulti-samples) (examples: 1-1 ionofcnyllc@verizon.net. ber then multi-sample num	1a,2-1b,3-1c). Could you plea	Equention 4/2/19 1:00AM HR 4/8/19
Collected By: Jamie Foster Relinquished By: Jamie Foster	Date: 04-05-		.00
Recieved by Lab:	Date: 4/6	10 11:115 An	4: V5 PH
	Page 1 Of 2	6 W	4-14-14

OrderID: 031907563

A2Z Environmental IIc.

P.O. Box 188 Pulaski, New York 13142 (315)527-8888

Chain of Custody Form

Location:	46 Division Street, Fort Plains				
Number:	A2Z04052019a	Page:	2	of	2

Sample #	material sampled	Location	F/NF/NOB	Analysis requested
21-10a	aluminum roof coat and tar	main roof - bottom layer	nob	tem
22-10b	aluminum roof coat and tar	main roof - bottom layer	nob	tem
23-11a	rolled roofing	main roof - top layer	nob	tem
24-11b	rolled roofing	main roof - top layer	nob	tem
25-12a	asphalt shingles and tar	side porch roof	nob	tem
26-12b	asphalt shingles and tar	side porch roof	nob	tem
				上

						· G	
-							
-							
	Instructions: 5 day turn aroun (number and letters indicate multi-sa copy of results to a2zconstructionofc First number is sample number the	nples) (examp nyllc@verizon.	oles: 1-1a,2-1b net.	,3-1c). Could yo	iples u please ema	HR 418	119
	Collected By: Jamie Foster	Date:	04-05-2019			7 7,0	11
	Relinquished By: Jamie Foster		04-05-2019		16:00	4:25	PA
	Recieved by Lab:	Date:	tillaks	11.03 Au			The state of the s
	I	age 2 Of	2				
-				The state of the s			



P.O. Box 188 Pulaski, New York 13142 (315)527-8888

Appendix D

Laboratory License and Certificate

NEW YORK STATE DEPARTMENT OF HEALTH WADSWORTH CENTER



Expires 12:01 AM April 01, 2020 Issued April 01, 2019

CERTIFICATE OF APPROVAL FOR LABORATORY SERVICE

Issued in accordance with and pursuant to section 502 Public Health Law of New York State

MR. JAMES HALL EMSL ANALYTICAL, INC 307 WEST 38TH STREET SUITE 901 NEW YORK, NY 10018

NY Lab Id No: 11506

is hereby APPROVED as an Environmental Laboratory for the category ENVIRONMENTAL ANALYSES SOLID AND HAZARDOUS WASTE All approved subcategories and/or analytes are listed below:

Miscellaneous

Asbestos in Friable Material

Item 198.1 of Manual

EPA 600/M4/82/020

Asbestos in Non-Friable Material-PLM

Item 198.6 of Manual (NOB by PLM)

Asbestos in Non-Friable Material-TEM

Item 198.4 of Manual

Asbestos-Vermiculite-Containing Material Item 198.8 of Manual

Serial No.: 59684