

# **REPORT OF PRE-RENOVATION ASBESTOS INSPECTION**



Location of Inspection:	20 Lake Street Richfield Springs, New York 13439
Client/ Building Owner:	Greater Mohawk Valley Land Bank 500 East Main Street, Suite 2A Little Falls, New York 13365
Alpine Project #:	19-23711-A
Material or Area Inspected:	Whole building
Asbestos Materials Tested:	Cement board, plaster, drywall compound, wall tile adhesive, 9″x9″ floor tile, floor tile, linoleum, flooring, sink insulation, roofing (assumed)
Non-Asbestos Containing	
Materials:	White blanket, ceramic floor tile, stone foundation mortar, stucco, paper over tarpaper, drywall, textured ceiling, ceramic wall tile & grout, carpet mastic, covebase & mastic, plastic wall tile adhesive, shower adhesive, black membrane (basement), tar paper (basement), wire insulation, window glazing, shingles
Date(s) of Inspection: Report Date:	January 10, 2019 January 29, 2019
Inspection Performed By:	Alpine Environmental Services, Inc. 438 New Karner Road Albany, New York 12205
Inspector(s):	Paul Van Zandt: NYSDOL Cert.#AH95-02581 NYS Department of Labor Certified Asbestos Inspector

#### Scope and Purpose

This report is intended to document the pre-renovation asbestos inspection of the building located at 20 Lake Street, Richfield Springs, New York.

"Asbestos containing materials", as defined by the United States Environmental Protection Agency (EPA), is any material containing greater than 1% by weight of asbestos. Friable samples (samples easily crushed/pulverized by hand pressure), were analyzed via Polarized Light Microscopy (PLM) and Non-Friable samples (samples not easily crushed/pulverized by hand pressure), were analyzed via Transmission Electron Microscopy (TEM) by EMSL Laboratory of New York, New York, a New York State Department of Health Approved Laboratory (ELAP #11506).

#### Description

The building was a vacant three-story, multi-family residential wood structure with a basement. The house was constructed in 1950. The heating system was forced air through metal ductwork or individual units in each apartment. The individual heating units in each apartment were contained in a closet. The closet was lined with cement board. No pipe insulation was observed. There was a stone foundation. No waterproofing was observed or suspected. Floors were wood and covered with vinyl tile, linoleum and other flooring. Walls and ceilings were plaster or drywall. No window or door caulk was observed.

#### Limitations

Quantities of asbestos containing materials were estimated and the user must field verify all quantities. The main roof was inaccessible at the time of inspection. There was a rear apartment on the first floor that was inaccessible at the time of inspection.

#### **Results of Asbestos Inspection**

Bulk samples were collected, as prescribed by US EPA ASHARA protocols for the number and types of samples. The following **asbestos containing materials** were found at 20 Lake Street, Richfield Springs, New York:

ACM (Sample #s)	Location	Quantity	Substrate	Friability	Condition		
	Floors						
9"x9" Floor Tile (13-01)	Basement	1,031 sq. ft.	Concrete	Non- Friable	Damaged		
9"x9" Floor Tile (14-01)	Unit 3 Kitchen (113)	100 sq. ft.	Wood	Non- Friable	Good		
Floor Tile (20-01)	Kitchen 200A	132 sq. ft.	Wood	Non- Friable	Good		
Floor Tile (21-01)	Bath 200	45 sq. ft.	Wood	Non- Friable	Good		
Linoleum (24-01)	Kitchen 203	170 sq. ft.	Wood	Non- Friable	Good		

ACM (Sample #s)	Location	Quantity	Substrate	Friability	Conditon				
	Flooring Cont'd								
Flooring (25-02)	Bath 204	40 sq. ft.	Wood	Non- Friable	Good				
Flooring (29-01)	Hall 207	55 sq. ft.	Wood	Non- Friable	Good				
	W	/alls/Ceilings							
Plaster	1 <sup>st</sup> Floor	3,015 sq. ft.	Wood	Friable	Good				
(7A-03,7A-04, 7A-05,7A-06)	2 <sup>nd</sup> Floor	10,256 sq. ft.	Wood	Friable	Damaged				
7A-03,7A-00)	3 <sup>rd</sup> Floor	9,400 sq. ft.	Wood	Friable	Damaged				
Drywall Compound (9-03)	1 <sup>st</sup> Floor	3,421 sq. ft.	Wood	Friable	Good				
Assumed	1 <sup>st</sup> Floor (Rear Apt.)	2,000 sq. ft.**	Wood	Friable	Unknown				
Wall Tile Adhesive	Kitchen 203	64 sq. ft.	Plaster	Non- Friable	Good				
(11M-01, 12M-01)	Bath 204	32 sq. ft.	Plaster	Non- Friable	Good				
		Misc.							
Cement Board	Basement	20 sq. ft.	Wood	Non- Friable	Good				
(1-01)	2 <sup>nd</sup> Floor Heater Closets	660 sq. ft.	Wood	Non- Friable	Good				
Sink Insulation (38-01)	Kitchen 203	4 sq. ft.	Metal	Non- Friable	Good				
	·	Roofing	·						
Roofing (Assumed to Contain Asbestos)	Roof	3,750 sq. ft.	Wood	Non- Friable	Good				

\*Quantities are estimates only and should be field verified by the user. \*\*Estimated because inaccessible at time of inspection.

Non-Asbestos		
Material	Locations	Sample #s
	Floors	
Ceramic Floor Tile	1 <sup>st</sup> Floor	3-01, 3-02
	Unit 1 Kitchen (100)	15-01, 15-02
12"x12" Floor Tile	Unit 1 Bath (102), Unit 1 Kitchen Countertop	16-01, 16-02
	Kitchen 209	32-01, 32-02
12"x12" Floor Tile &	Unit 2 Entry (Vestibule)	17-01, 17-02
Mastic	Kitchen 205	27-01, 27-02
	Unit 2 Living Room (104)	18-01, 18-02
Colf Ctick Floor Tile	Unit 3 (Bath 114)Bath	19-01, 19-02
Self Stick Floor Tile	Room 202	23-01, 23-02
	Kitchen 207	30-01, 30-02
Linglaure	Room 201 Closet	22-01, 22-02
Linoleum	Room 204 Closet	26-01, 26-02
Flooring	Hall 205 (206)	28-01, 28-02
Flooring	Bath 208	31-01, 31-02
Carpet Mastic	Unit 1 (LR 101), Unit 2 (LR 104)	33-01, 33-02
Covebase & Mastic	Unit 1 Kitchen (100), Room 201	34-01, 34-02
	Walls	
Stone Foundation Mortar	Basement	4-01, 4-02
Stucco	Basement	5-01, 5-02
Paper over Tar Paper	Basement	6-01, 6-02
Drywall	Unit 1 (Kitchen 100), Unit 3 (Bedroom 111)	8-01, 8-02
	Kitchen 203 Backsplash	11-01, 11-02,
Ceramic Wall Tile &		11G-01, 11G-02
Grout	Bath 204	12-01, 12-02,
		12G-01,12G-02
Plastic Wall Tile Adhesive	Unit 1 Bath (102), Bath 206	35-01, 35-02
Tar Paper	Basement on Walls	39-01, 39-02
	Ceilings	-
Textured Ceiling	Unit 1 Living Room &Bedroom, Unit 3 Living Room	10-01, 10-02, 10-03
	Misc.	
White Blanket	Basement on Duct Adjacent Furnace	2-01,2-02
Shower Adhesive	Unit 1 Bath (102)	36-01, 36-02
Black Membrane	Basement Floor in Roll	37-01, 37-02
Wire Insulation	3 <sup>rd</sup> Floor	40-01, 40-02
	Exterior	
Window Glazing	Exterior	41-01, 41-02
Window Glazing Shingle	Exterior Roofing Side Porch Roof	41-01, 41-02

## The following materials were sampled and determined not to contain asbestos:

#### **Conclusion & Recommendations**

Any materials not sampled during this inspection should be considered suspect unless sampled and determined to be non-asbestos. All asbestos containing materials must be abated prior to the demolition/renovation of any of the structures unless performed under a variance issued by the NYS Department of Labor. Disturbance/Abatement of any asbestos containing materials, as well as necessary air monitoring, must be performed by a NYS DOL licensed contractor, in accordance with state and federal regulations (NYS DOL ICR 56 and US EPA 40 CFR).

If Alpine Environmental Services can be of further assistance on this matter, please contact Craig Petreikis at either (518) 250-4047 ext. 313 or craigp@alpineenv.com.

Sincerely, Alpine Environmental Services, Inc.

Pelve th

Paul Van Zandt NYS Dept. of Labor Asbestos Inspector

Enclosures: Results, NYSDOL Handling License(s), NYSDOL Handling Certificate(s), NYSDOH ELAP License(s)



9"x9" Floor Tile - Basement



9"x9" Floor Tile – Kitchen 113



Floor Tile (Bottom Layer) – Kitchen 200



Linoleum, Sink Insulation & Wall Tile Adhesive – Kitchen 203



Plaster – Room 207



Cement Board – Room 200 Heater Closet



Cement Board – Basement Ceiling

Initial report from: 01/16/2019 17:49:48

Phone:	(518) 250-4047
Fax:	
Received Date:	01/12/2019 11:17 AM
Analysis Date:	01/16/2019
Collected Date:	01/10/2018

Project: 18-23711-A/ 20 LAKE ST, RICHFIELD SPRINGS, NY

Albany, NY 12205

### Test Report: Asbestos Analysis of Bulk Material

	Analyzed			Non-Asbestos	
Test	Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 1-01		Description	ROOM 200 FURNA	CE CLOSET - CEMENT BOARD	
031900712-0	001	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	Gray	None	76.00% Non-fibrous (other)	24.00% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
EM NYS 198.4 NOB					Not Analyzed
Sample ID 1-02		Description	ROOM 202 FURNA	CE CLOSET - CEMENT BOARD	
031900712-0	002	Homogeneity			
PLM NYS 198.1 Friable	01/16/2019				Positive Stop (Not Analyzed)
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
EM NYS 198.4 NOB					Not Analyzed
Sample ID 2-01		Description	BASEMENT ON DU	CT ADJ FURNACE - WHITE BLANKET	
031900712-0	003	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	White 92.00	0% Min. Wool	8.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
EM NYS 198.4 NOB					Not Analyzed
Sample ID 2-02		Description	BASEMENT ON DU	CT ADJ FURNACE - WHITE BLANKET	
031900712-0	004	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	White 82.00	0% Min. Wool	18.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 3-01		Description	ROOM 204 BATH -	CERAMIC FLOOR TILE	
031900712-0	005	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	Brown/ White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
EM NYS 198.4 NOB					Not Analyzed



Tel/Fax: (212) 290-0051 / (212) 290-0058 http://www.EMSL.com / manhattanlab@emsl.com

# Test Report: Asbestos Analysis of Bulk Material

	Analyzed		Non	-Asbestos	
Test	Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 3-02		Description	ROOM 204 BATH - CERA	MIC FLOOR TILE	
031900712	-0006	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	Brown		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 4-01		Description	BASEMENT - STONE FO	UNDATION MORTAR	
031900712	-0007	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	Brown		70.00% Non-fibrous (other) 30.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 4-02		Description	BASEMENT - STONE FO	UNDATION MORTAR	
031900712	-0008	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	Gray 3.00%	% Cellulose	25.00% Ca Carbonate 37.00% Non-fibrous (other) 35.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 5-01		Description	BASEMENT - STUCCO		
031900712	-0009	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	Gray 18.00%	% Cellulose	40.00% Gypsum 42.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 5-02		Description	BASEMENT - STUCCO		
031900712	-0010	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	Gray		60.00% Gypsum 40.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 6-01		Description	BASEMENT WALL OVER	TAR PAPER - PAPER	
031900712	-0011	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable Inseparable paint / coatin	01/16/2019 ng layer included in a		% Cellulose	18.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed



	Anolyzed		N	on-Asbestos	
Test	Analyzed Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 6-02		Description	BASEMENT WALL OV	ER TAR PAPER - PAPER	
031900712-0	012	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	Gray 55.00	% Cellulose	30.00% Ca Carbonate 14.22% Non-fibrous (other)	0.78% Chrysotile
Inseparable paint / coating	g layer included in a	analysis			
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 7A-01		Description	ROOM 200 - PLASTER	RSUBSTRATE	
031900712-0	013	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	Gray		45.00% Gypsum 55.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 7B-01		Description	ROOM 200 - PLASTER	R SKIM COAT	
031900712-0	014	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	White		52.00% Ca Carbonate 48.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 7A-02		Description	ROOM 203 - PLASTER	R SUBSTRATE	
031900712-0	015	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	Gray 4.00	% Hair	66.00% Non-fibrous (other) 30.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 7B-02		Description	ROOM 203 - PLASTER	R SKIM COAT	
031900712-0	016	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	White		40.00% Ca Carbonate 55.00% Non-fibrous (other) 5.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 7A-03		Description	ROOM 206 - PLASTER	R SUBSTRATE	
031900712-0	017	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	Gray	None	59.20% Non-fibrous (other) 38.00% Quartz	2.80% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
					Not Analyzed

Initial report from: 01/16/2019 17:49:48



	Analyzed		N	on-Asbestos	
Test	Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 7B-03		Description	ROOM 206 - PLASTER	R SKIM COAT	
031900712-00	018	Homogeneity			
PLM NYS 198.1 Friable	01/16/2019				Positive Stop (Not Analyzed)
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 7A-04		Description	ROOM 207 - PLASTER	R SUBSTRATE	
031900712-00	019	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	Gray	None	57.50% Non-fibrous (other) 40.00% Quartz	2.50% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 7B-04		Description	ROOM 207 - PLASTER	R SKIM COAT	
031900712-00	020	Homogeneity			
PLM NYS 198.1 Friable	01/16/2019				Positive Stop (Not Analyzed)
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 7A-05		Description	ROOM 209 - PLASTER	R SUBSTRATE	
031900712-00	021	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	Gray 4.00	% Cellulose	49.70% Non-fibrous (other) 44.00% Quartz	2.30% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 7B-05		Description	ROOM 209 - PLASTER	R SKIM COAT	
031900712-00	022	Homogeneity			
PLM NYS 198.1 Friable	01/16/2019				Positive Stop (Not Analyzed)
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 7A-06		Description	ROOM 300 - PLASTER	R SUBSTRATE	
031900712-00	023	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	Gray	None	53.40% Non-fibrous (other) 45.00% Quartz	1.60% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed



	Applyzod		Non-Asbestos			
Test	Analyzed Date	Color	Fibrous	Non-Fibrous	Asbestos	
Sample ID 7B-06		Description	ROOM 300 - PLASTE	R SKIM COAT		
031900712-00	)24	Homogeneity				
PLM NYS 198.1 Friable	01/16/2019				Positive Stop (Not Analyzed)	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB					Not Analyzed	
TEM NYS 198.4 NOB					Not Analyzed	
Sample ID 7A-07		Description	ROOM 303 - PLASTE	R SUBSTRATE		
031900712-00	)25	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	01/16/2019	Gray	None	44.23% Non-fibrous (other) 55.00% Quartz	0.77% Chrysotile	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB					Not Analyzed	
TEM NYS 198.4 NOB					Not Analyzed	
Sample ID 7B-07		Description	ROOM 303 - PLASTE	R SKIM COAT		
031900712-00	)26	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	01/16/2019	White		65.00% Ca Carbonate 35.00% Non-fibrous (other)	None Detected	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB					Not Analyzed	
TEM NYS 198.4 NOB					Not Analyzed	
Sample ID 8-01		Description	UNIT 1 - DRYWALL			
031900712-00	)27	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	01/16/2019	Brown/ Gray 12.0	00% Cellulose	62.00% Gypsum 26.00% Non-fibrous (other)	None Detected	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB					Not Analyzed	
TEM NYS 198.4 NOB					Not Analyzed	
Sample ID 8-02		Description	UNIT 3 - DRYWALL			
031900712-00	)28	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	01/16/2019	Gray 5.0	00% Cellulose	65.00% Gypsum 30.00% Non-fibrous (other)	None Detected	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB					Not Analyzed	
TEM NYS 198.4 NOB					Not Analyzed	
Sample ID 9-01		Description	UNIT 1 - DRYWALL C	OMPOUND		
031900712-00	)29	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	01/16/2019	White		57.00% Ca Carbonate 5.00% Mica 38.00% Non-fibrous (other)	None Detected	
PLM NYS 198.6 VCM				· · · · · ·	Not Analyzed	
PLM NYS 198.6 NOB					Not Analyzed	
					Not Analyzed	



	Anolyzed		N	on-Asbestos	
Test	Analyzed Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 9-02		Description	UNIT 2 - DRYWALL CO	DMPOUND	
031900712-0	030	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	White		58.00% Ca Carbonate 4.00% Mica 38.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 9-03		Description	UNIT 3 - DRYWALL CO	DMPOUND	
031900712-0	031	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	Tan	None	5.00% Mica 91.80% Non-fibrous (other)	3.20% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 9-04		Description	ROOM 200 - DRYWAL	L COMPOUND	
031900712-0	032	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	Tan/ White	None	6.00% Mica 91.80% Non-fibrous (other)	2.20% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 9-05		Description	ROOM 202 - DRYWAL	L COMPOUND	
031900712-0	033	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	White		65.00% Ca Carbonate 6.00% Mica 29.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 10-01		Description	UNIT 1 LIVING ROOM	- TEXTURED CEILING	
031900712-0	034	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	White 2.00	0% Fibrous (other)	83.00% Non-fibrous (other) 15.00% Perlite	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 10-02		Description	UNIT 1 BEDROOM - TI	EXTURED CEILING	
031900712-0	035	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	White 2.00	0% Fibrous (other)	86.00% Non-fibrous (other) 12.00% Perlite	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial report from: 01/16/2019 17:49:48



	Analyzed		Non-Asl	bestos	
Test	Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 10-03		Description	UNIT 3 LIVING ROOM - TEX	TURED CEILING	
031900712-0	036	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	White		65.00% Ca Carbonate 35.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 11-01		Description	203 KITCHEN BACKSPLASH	I - CERAMIC WALL TILE	
031900712-0	037	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	White		93.00% Non-fibrous (other) 7.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 11-02		Description	203 KITCHEN BACKSPLASH	I - CERAMIC WALL TILE	
031900712-0	038	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	White		90.00% Non-fibrous (other) 10.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 11G-01		Description	203 KITCHEN BACKSPLASH	I - WALL TILE GROUT	
031900712-0	039	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	White		45.00% Ca Carbonate 55.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 11G-02		Description	203 KITCHEN BACKSPLASH	I - WALL TILE GROUT	
031900712-0	040	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	White		55.00% Ca Carbonate 45.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 12-01		Description	204 BATH - CERAMIC WALL	TILE	
031900712-0	041	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	White/ Green		88.00% Non-fibrous (other) 12.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed



	Analyzed		No	on-Asbestos	
Test	Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 12-02		Description	204 BATH - CERAMIC	WALL TILE	
031900712-0	042	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	White		90.00% Non-fibrous (other) 10.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 12G-01		Description	204 BATH - WALL TILE	GROUT	
031900712-0	043	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	White		52.00% Ca Carbonate 48.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 12G-02		Description	204 BATH - WALL TILE	GROUT	
031900712-0	044	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	01/16/2019	White		55.00% Ca Carbonate 45.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
FEM NYS 198.4 NOB					Not Analyzed

EMSL Analytical, Inc. 307 West 38th Street New York, NY 10018 Tel/Fax: (212) 290-0051 / (212) 290-0058 http://www.EMSL.com / manhattanlab@emsl.com EMSL Order: 031900712 Customer ID: ALPI50 Customer PO: Project ID:

## Test Report: Asbestos Analysis of Bulk Material

The samples in this report were submitted to EMSL for analysis by Asbestos Analysis of Bulk Materials via NYS ELAP Approved Methods . The reference number for these samples is the EMSL Order ID above. Please use this reference number when calling about these samples.

#### **Report Comments:**

Sample Receipt Date: 1/12/2019 Analysis Completed Date: 1/16/2019

Analyst(s):

Krystal Harris PLM NYS 198.1 Friable (15)

Samples reviewed and approved by:

Sample Receipt Time: 11:17 AM

Analysis Completed Time: 1:26 AM

Shahrakur Mahmud PLM NYS 198.1 Friable (24)

James Hall, Laboratory Manager or Other Approved Signatory

NOB = Non Friable Organically Bound N/A = Not Applicable VCM = Vermiculite Containing Material

-In New York State, TEM is currently the only method that can be used to determine if NOB materials can be considered or treated as non -asbestos containing. All samples examined for the presence of vermiculite when analyzed via NYS 198.1.

-NYS Guidelines for Vermiculite containing samples are available at http://www.wadsworth.org/labcert/elapcert/forms/VermiculiteInterimGuidance\_Rev070913.pdf EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples were received in good condition unless otherwise noted.

This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. This report may contain data that is not covered by the NVLAP accreditation.

Samples analyzed by EMSL Analytical, Inc. New York, NY NYS ELAP 11506

Initial report from: 01/16/2019 17:49:48

OrderID: 031900712
438 New Karner Road
Albany, NY 12205

131900712

2

# **CHAIN OF CUSTODY**

Client: Alpine Environmental Services, Inc.

	438	New	Karner	Road	
--	-----	-----	--------	------	--

Albany, NY 12205

Contact: Paul Van Zandt

Phone/Email: 518 250-4047 paulv@alpineenv.com Delivery: Fed Ex 7741 7004 5933

Turnaround Time: 72Hr

Project: 20 Lake St, Richfield Springs, NY Project Number: 18-23711-A Sampled By: P. Van Zandt Date / Time Collected: 01/10/18 Delivery: Fed Ex 7741 7004 5933

Log No.	Sample No.	Sample Location	Sample Material	Analysis Performed	Notes
	1-01	Room 200 Furnace Closet	Cement Board	NYS PLM	Stop at 1 <sup>st</sup> Positive
	1-02	Room 202 Furnace Closet	Cement Board	Gir	1-01 to 1-02
	2-01	Basement on Duct Adj. Furnace	White Blanket	-1	Stop at 1 <sup>st</sup> Positive
	2-02	Basement on Duct Adj. Furnace	White Blanket		2-01 to 2-02
	3-01	Room 204 Bath	Ceramic Floor Tile		Stop at 1 <sup>st</sup> Positive
	3-02	Room 204 Bath	Ceramic Floor Tile	2	3-01 to 3-02
	4-01	Basement	Stone Foundation Mortar		Stop at 1 <sup>st</sup> Positive
	4-02	Basement	Stone Foundation Mortar		4-01 to 4-02
	5-01	Basement	Stucco		Stop at 1 <sup>st</sup> Positive
	5-02	Basement	Stucco		5-01 to 5-02
	6-01	Basement Wall Over Tar Paper	Paper		Stop at 1 <sup>st</sup> Positive
	6-02	Basement Wall Over Tar Paper	Paper		6-01 to 6-02

Disposition of Samples: Accept\_\_\_\_ Reject\_\_\_ Explain\_\_\_\_ Comments:

Karty 1/100

Relinquished By:	Received By:	Dat	e:	1	Time:
PUV=246	Jucho	1	12	19	11:17Am
			1		

4

Page 1 of 4

1/16/19 2123m

Page 1 Of

OrderID: 031900712 Appine Environmental Services, Inc.
438 New Karner Road
Albany, NY 12205

# 031900712

# **CHAIN OF CUSTODY**

Client: Alpine Environmental Services, Inc.

438	New	Karner	Road	_	
450	11011	ranner	Road		

Albany, NY 12205 Contact: Paul Van Zandt

Contact. Faul van Zandt

Phone/Email: 518 250-4047 paulv@alpineenv.com

Turnaround Time: 72Hr

	Project: 20 Lake St, Richfield Springs, NY	14
_	Project Number: 18-23711-A	in the second se
	Sampled By: P. Van Zandt	En la
	Date / Time Collected: 01/10/18	
n	Delivery: Fed Ex 7741 7004 5933	51
		22
-		1

Log No.	Sample No.	Sample Location	Sample Material	Analysis Performed	Notes	
	7A-01	Room 200	Plaster Substrate	NYS PLM	Stop at 1 <sup>st</sup> Positive	
	7B-01	Room 200	Plaster Skim Coat		7A-01 to 7A-0	
	7A-02	Room 203	Plaster Substrate		Stop at 1 <sup>st</sup> Positive	
	7B-02	Room 203	Plaster Skim Coat		7A-02 to 7B-02	
3	7A-03	Room 206	Plaster Substrate		Stop at 1 <sup>st</sup> Positive	
	7B-03	Room 206	Plaster Skim Coat	te pat	7A-03 to 7B-0	
	7A-04	Room 207	Plaster Substrate		Stop at 1 <sup>st</sup> Positive	
	7B-04	Room 207	Plaster Skim Coat		7A-04 to 7B-0	
	7A-05	Room 209	Plaster Substrate		Stop at 1 <sup>st</sup> Positive	
	7B-05	Room 209	Plaster Skim Coat		7A-05 to 7B-0	
	7A-06	Room 300	Plaster Substrate		Stop at 1 <sup>st</sup> Positive	
	7B-06	Room 300	Plaster Skim Coat		7A-06 to 7B-0	

Disposition of Samples: Accept\_\_\_\_ Reject\_\_\_ Explain\_\_\_ Comments:

Kargy live

Relinquished By:	Received By:	Date:	Time:
PUVEZA6	Questio	1/2/19	11:17Am
		1º - E -	

4

Page 2 of 4

OrderID: 031900712 rvices, Inc. 438 New Karner Road Albany, NY 12205

031900712

# **CHAIN OF CUSTODY**

Client: Alpine Environmental Services, Inc.	Project: 20 Lake St, Richfield Springs, N	ΙY	
438 New Karner Road	Project Number: 18-23711-A		ENT
Albany, NY 12205	Sampled By: P. Van Zandt	5	69
Contact: Paul Van Zandt	Date / Time Collected: 01/10/18		225
Phone/Email: 518 250-4047 paulv@alpineenv.com	Delivery: Fed Ex 7741 7004 5933	o f	19
Turnaround Time: 72Hr		1 1 L J	

Log No.	Sample No.	Sample Location	Sample Material	Analysis Performed	Notes
	7A-07	Room 303	Plaster Substrate	NYS PLM	Stop at 1 <sup>st</sup> Positive
	7B-07	Room 303	Plaster Skim Coat		7A-07 to 7B-07
	8-01	Unit 1	Drywall		Stop at 1 <sup>st</sup> Positive
	8-02	Unit 3	Drywall		8-01 to 8-02
	9-01	Unit 1	Drywall Compound		
	9-02	Unit 2	Drywall Compound		
	9-03	Unit 3	Drywall Compound		
	9-04	Room 200	Drywall Compound		
	9-05	Room 202	Drywall Compound		
	10-01	Unit 1 Living Room	Textured Ceiling		Stop at 1 <sup>st</sup> Positive
	10-02	Unit 1 Bedroom	Textured Ceiling		10-01 to 10-0.
	10-03	Unit 3 Living Room	Textured Ceiling		

Disposition of Samples: Accept\_\_\_\_ Reject\_\_\_ Explain\_\_\_ Comments:

Relinquished By: Received By: Time: Date: PIVE 200 Runio 11:17AM

Page 3 of 4

D21	900	712
021	100	110

OrderID: 031900712 Applie Environmental services, In	c.
438 New Karner Road	
Albany, NY 12205	

# **CHAIN OF CUSTODY**

Albany, NY 12205	-	1.11
<u>CHAIN</u>	OF CUSTODY	S
Client: Alpine Environmental Services, Inc.	Project: 20 Lake St, Richfield Springs, NY	2013
438 New Karner Road	Project Number: 18-23711-A	
Albany, NY 12205	Sampled By: P. Van Zandt	No.
Contact: Paul Van Zandt	Date / Time Collected: 01/10/18	OF
Phone/Email: 518 250-4047 paulv@alpineenv.com	Delivery: Fed Ex 7741 7004 5933	I'm .
Turnaround Time: 72Hr		0)

Log No.	Sample No.	Sample Location	Sample Material	Analysis Performed	Notes
	11-01	203 Kitchen Backsplash	Ceramic Wall Tile	NYS PLM	Stop at 1 <sup>st</sup> Positive
	11-02	203 Kitchen Backsplash	Ceramic Wall Tile		11-01 to 11-02
1	11G-01	203 Kitchen Backsplash	Wall Tile Grout		Stop at 1 <sup>st</sup> Positive
	11G-02	203 Kitchen Backsplash	Wall Tile Grout		11G-01 to 11G-02
	12-01	204 Bath	Ceramic Wall Tile		Stop at 1 <sup>st</sup> Positive
	12-02	204 Bath	Ceramic Wall Tile		12-01 to 12-02
	12G-01	204 Bath	Wall Tile Grout		Stop at 1 <sup>st</sup> Positive
	12G-02	204 Bath	Wall Tile Grout		12G-01 to 12G-02

Disposition of Samples: Accept\_\_\_\_ Reject\_\_\_ Explain\_ Comments:

Kall Ille

Relinquished By:	Received By:	Date:	Time:
PIVEZ66	Euchio,	1/12/19	11:17Am

4

Page 4 of 4

## **EMSL Analytical, Inc.** 307 West 38th Street New York, NY 10018

Tel/Fax: (212) 290-0051 / (212) 290-0058 http://www.EMSL.com / manhattanlab@emsl.com

 Phone:
 (518) 250-4047

 Fax:
 01/12/2019 11:17 AM

 Analysis Date:
 01/14/2019 - 01/16/2019

 Collected Date:
 01/10/2019

Project: 18-23711-A/ 20 LAKE ST, RICHFIELD SPRINGS, NY

#### Test Report: Asbestos Analysis of Bulk Material

	Analyzed				
Test	Date	Color	Fibrous	Non-Fibrous	Asbestos
ample ID 11M-01		Description	203 KITCHEN BACK	SPLASH - WALL TILE ADHESIVE	
031900714-	0001	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Yellow		100.00% Other	Inconclusive: None Detected
EM NYS 198.4 NOB	01/15/2019	Yellow	None	98.90% Other	<1.00% Anthophyllite <1.00% Chrysotile 1.1% Total
Sample ID 11M-02		Description	203 KITCHEN BACK	SPLASH - WALL TILE ADHESIVE	
031900714-	0002	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Yellow		100.00% Other	Inconclusive: None Detected
EM NYS 198.4 NOB	01/15/2019				Positive Stop (Not Analyzed)
ample ID 12M-01		Description	204 BATH - WALL TI	LE ADHESIVE	
031900714-	0003	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Yellow	None	98.50% Other	1.50% Chrysotile
EM NYS 198.4 NOB	01/14/2019				Positive Stop (Not Analyzed)
Sample ID 12M-02		Description	204 BATH - WALL TI	LE ADHESIVE	
031900714-	0004	Homogeneity			
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019				Positive Stop (Not Analyzed)
EM NYS 198.4 NOB	01/14/2019				Positive Stop (Not Analyzed)
ample ID 13M-01		Description	BASEMENT - FLOOP	R TILE MASTIC	
031900714-	0005	Homogeneity	Heterogeneous		
LM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Black		100.00% Other	Inconclusive: None Detected
EM NYS 198.4 NOB	01/14/2019				Positive Stop (Not Analyzed)



## Attention: Alpine Environmental Services 438 New Karner Road

Albany, NY 12205



307 West 38th Street New York, NY 10018 Tel/Fax: (212) 290-0051 / (212) 290-0058 http://www.EMSL.com / manhattanlab@emsl.com

## Test Report: Asbestos Analysis of Bulk Material

	Analyzed		I	Non-Asbestos	
Test	Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 13-01		Description	BASEMENT - 9"X9" F	LOOR TILE	
031900714-	0006	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Beige	None	96.30% Other	3.70% Chrysotile
TEM NYS 198.4 NOB	01/14/2019				Positive Stop (Not Analyzed)
Sample ID 13M-02		Description	BASEMENT - FLOOR	R TILE MASTIC	
031900714-	0007	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Black	None	100.00% Other	Inconclusive : <1.00% Chrysotile
TEM NYS 198.4 NOB	01/14/2019				Positive Stop (Not Analyzed)
Sample ID 13-02		Description	BASEMENT - 9"X9" F	LOOR TILE	
031900714-	0008	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Beige	None	95.40% Other	4.60% Chrysotile
TEM NYS 198.4 NOB	01/14/2019				Positive Stop (Not Analyzed)
Sample ID 14M-01		Description	UNIT 3 KITCHEN - FL	OOR TILE MASTIC	
031900714-	0009	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Black	None	100.00% Other	Inconclusive : <1.00% Chrysotile
TEM NYS 198.4 NOB	01/14/2019				Positive Stop (Not Analyzed)
Sample ID 14-01		Description	UNIT 3 KITCHEN - 9"	X9" FLOOR TILE	
031900714-	0010	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Beige	None	97.70% Other	2.30% Chrysotile
TEM NYS 198.4 NOB	01/14/2019				Positive Stop (Not Analyzed)
Sample ID 14M-02		Description	UNIT 3 KITCHEN - FL	OOR TILE MASTIC	
031900714-	0011	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Black		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/14/2019				Positive Stop (Not Analyzed)



307 West 38th Street New York, NY 10018 Tel/Fax: (212) 290-0051 / (212) 290-0058 http://www.EMSL.com / manhattanlab@emsl.com

## Test Report: Asbestos Analysis of Bulk Material

	Apalyzod		Ν	Ion-Asbestos	
Test	Analyzed Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 14-02		Description	UNIT 3 KITCHEN - 9">	X9" FLOOR TILE	
031900714-	0012	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Beige	None	96.90% Other	3.10% Chrysotile
TEM NYS 198.4 NOB	01/14/2019				Positive Stop (Not Analyzed)
Sample ID 15-01		Description	UNIT 1 KITCHEN - 12	"X12" FLOOR TILE	
031900714-	0013	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	White		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	White		100.00% Other	None Detected
Sample ID 15-02		Description	UNIT 1 KITCHEN - 12	"X12" FLOOR TILE	
031900714-	0014	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	White		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	White		100.00% Other	None Detected
Sample ID 16-01		Description	UNIT 1 BATH - FLOOP	R TILE	
031900714-	0015	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Gray		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Gray		100.00% Other	None Detected
Sample ID 16-02		Description	UNIT 1 KITCHEN COU	JNTERTOP - FLOOR TILE	
031900714-	0016	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Gray		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Gray		100.00% Other	None Detected
Sample ID 17-01-Floo	or Tile	Description	UNIT 2 ENTRY - 12"X	12" FLOOR TILE & MASTIC	
031900714-	0017	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	White		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	White		100.00% Other	None Detected



307 West 38th Street New York, NY 10018 Tel/Fax: (212) 290-0051 / (212) 290-0058 http://www.EMSL.com / manhattanlab@emsl.com EMSL Order: 031900714 Customer ID: ALPI50 Customer PO: Project ID:

# Test Report: Asbestos Analysis of Bulk Material

	Analyzed		Ν	Ion-Asbestos	
Test	Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 17-01-Mas	tic	Description	UNIT 2 ENTRY - 12"X	12" FLOOR TILE & MASTIC	
031900714-0	0017A	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Black		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Black		100.00% Other	None Detected
Sample ID 17-02-Floo	r Tile	Description	UNIT 2 KITCHEN - 12	"X12" FLOOR TILE & MASTIC	
031900714-0	0018	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	White		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	White		100.00% Other	None Detected
Sample ID 17-02-Mas	tic	Description	UNIT 2 KITCHEN - 12	"X12" FLOOR TILE & MASTIC	
031900714-0	0018A	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Black		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Black		100.00% Other	None Detected
Sample ID 18-01		Description	UNIT 2 LIVING ROOM	1 - SELF STICK FLOOR TILE	
031900714-0	0019	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Tan		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Tan		100.00% Other	None Detected
Sample ID 18-02		Description	UNIT 2 LIVING ROOM	1 - SELF STICK FLOOR TILE	
031900714-0	0020	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Tan		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Tan		100.00% Other	None Detected
Sample ID 19-01		Description	UNIT 3 BATH - SELF S	STICK FLOOR TILE	
031900714-0	0021	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Green		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Green		100.00% Other	None Detected



307 West 38th Street New York, NY 10018 Tel/Fax: (212) 290-0051 / (212) 290-0058 http://www.EMSL.com / manhattanlab@emsl.com EMSL Order: 031900714 Customer ID: ALPI50 Customer PO: Project ID:

# Test Report: Asbestos Analysis of Bulk Material

	Apolyzod			Non-Asbestos	
Test	Analyzed Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 19-02		Description	UNIT 3 BATH - SELF	STICK FLOOR TILE	
031900714-	0022	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Green		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Green		100.00% Other	None Detected
Sample ID 20-01		Description	200 KITCHEN BOTT	OM LAYER - FLOOR TILE	
031900714-	0023	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Beige	None	96.10% Other	3.90% Chrysotile
TEM NYS 198.4 NOB	01/14/2019				Positive Stop (Not Analyzed)
Sample ID 20-02		Description	200 KITCHEN MIDD	LE LAYER - FLOOR TILE	
031900714-	0024	Homogeneity			
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019				Positive Stop (Not Analyzed)
TEM NYS 198.4 NOB	01/14/2019				Positive Stop (Not Analyzed)
Sample ID 20-03		Description	200 KITCHEN TOP L	AYER - FLOOR TILE	
031900714-	0025	Homogeneity			
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019				Positive Stop (Not Analyzed)
TEM NYS 198.4 NOB	01/14/2019				Positive Stop (Not Analyzed)
Sample ID 21-01		Description	200 BATH BOTTOM	LAYER - FLOOR TILE	
031900714-	0026	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	White	None	93.10% Other	6.90% Chrysotile
TEM NYS 198.4 NOB	01/14/2019				Positive Stop (Not Analyzed)
Sample ID 21-02		Description	200 BATH TOP LAYE	ER - FLOOR TILE	
031900714-	0027	Homogeneity			
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019				Positive Stop (Not Analyzed)
TEM NYS 198.4 NOB	01/14/2019				Positive Stop (Not Analyzed)



307 West 38th Street New York, NY 10018 Tel/Fax: (212) 290-0051 / (212) 290-0058 http://www.EMSL.com / manhattanlab@emsl.com

# Test Report: Asbestos Analysis of Bulk Material

	Analyzed		Non-As		
Test	Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 22-01		Description	201 CLOSET - LINOLEUM		
031900714	-0028	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Brown		100.00% Other	Inconclusive: None Detected
Final Residue <1% of or	iginal subsample				
EM NYS 198.4 NOB	01/15/2019	Brown		100.00% Other	None Detected
Sample ID 22-02		Description	201 CLOSET - LINOLEUM		
031900714	-0029	Homogeneity	Homogeneous		
LM NYS 198.1 Friable					Not Analyzed
LM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Brown		100.00% Other	Inconclusive: None Detected
Final Residue <1% of or	iginal subsample				
EM NYS 198.4 NOB	01/15/2019	Brown		100.00% Other	None Detected
Sample ID 23-01		Description	202 - SELF STICK FLOOR T	ILE	
031900714	-0030	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Green		100.00% Other	Inconclusive: None Detected
Final Residue <1% of or	iginal subsample				
TEM NYS 198.4 NOB	01/15/2019	Green		100.00% Other	None Detected
Sample ID 23-02		Description	202 - SELF STICK FLOOR T	ILE	
031900714	-0031	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Green		100.00% Other	Inconclusive: None Detected
Final Residue <1% of or	iginal subsample				
TEM NYS 198.4 NOB	01/15/2019	Green		100.00% Other	None Detected
Sample ID 24-01		Description	203 KITCHEN - LINOLEUM		
031900714	-0032	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	White	None	98.80% Other	1.20% Chrysotile
TEM NYS 198.4 NOB	01/14/2019				Positive Stop (Not Analyzed)
		Description	203 KITCHEN - LINOLEUM		
Sample ID 24-02		Homogeneity			
Sample ID 24-02 031900714	-0033	nonlogeneity			
•		nonlogeneity			Not Analyzed
031900714 PLM NYS 198.1 Friable		Tomogeneity			Not Analyzed Not Analyzed
031900714		Tomogeneity			-



307 West 38th Street New York, NY 10018 Tel/Fax: (212) 290-0051 / (212) 290-0058 http://www.EMSL.com / manhattanlab@emsl.com

# Test Report: Asbestos Analysis of Bulk Material

	Analyzed		N	Ion-Asbestos	
Test	Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 25-01		Description	204 BATH BOTTOM L	AYER - FLOORING	
031900714-	0034	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB Final Residue <1% of ori	01/14/2019 ginal subsample	Tan		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Tan		100.00% Other	None Detected
Sample ID 25-02		Description	204 BATH TOP LAYER	R - FLOORING	
031900714-	0035	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Tan 1.50	% Fibrous (other)	98.50% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Tan	None	98.90% Other	1.10% Anthophyllite
Sample ID 26-01		Description	204 CLOSET - LINOLE	EUM	
031900714-	0036	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Blue		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Blue		100.00% Other	None Detected
Sample ID 26-02		Description	204 CLOSET - LINOLE	EUM	
031900714-	0037	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Blue		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Blue		100.00% Other	None Detected
Sample ID 27-01		Description	205 KITCHEN - 12"X12	2" FLOOR TILE & MASTIC	
031900714-	0038	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Gray		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Gray		100.00% Other	None Detected
Sample ID 27-01-Mas	tic	Description	205 KITCHEN - 12"X12	2" FLOOR TILE & MASTIC	
031900714-	0038A	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Yellow 3.40	% Glass	96.60% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Yellow		100.00% Other	None Detected



307 West 38th Street New York, NY 10018 Tel/Fax: (212) 290-0051 / (212) 290-0058 http://www.EMSL.com / manhattanlab@emsl.com EMSL Order: 031900714 Customer ID: ALPI50 Customer PO: Project ID:

## Test Report: Asbestos Analysis of Bulk Material

	Analyzed	Non-Asbestos			
Test	Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 27-02		Description	205 KITCHEN - 12"X1	2" FLOOR TILE & MASTIC	
031900714-	0039	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Gray		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Gray		100.00% Other	None Detected
Sample ID 27-02-Mas	tic	Description	205 KITCHEN - 12"X1	2" FLOOR TILE & MASTIC	
031900714-	0039A	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Yellow		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Yellow		100.00% Other	None Detected
Sample ID 28-01		Description	205 HALL BOTTOM L	AYER - FLOORING	
031900714-	0040	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Gray		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Gray		100.00% Other	None Detected
Sample ID 28-02		Description	205 HALL TOP LAYER	R - FLOORING	
031900714-	0041	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	White		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	White		100.00% Other	None Detected
Sample ID 29-01		Description	207 HALL BOTTOM L	AYER - FLOORING	
031900714-	0042	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Gray		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/14/2019				Positive Stop (Not Analyzed)
Sample ID 29-02		Description	207 HALL TOP LAYER	R - FLOORING	
031900714-	0043	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Gray	None	94.60% Other	5.40% Chrysotile
TEM NYS 198.4 NOB	01/14/2019				Positive Stop (Not Analyzed)



307 West 38th Street New York, NY 10018 Tel/Fax: (212) 290-0051 / (212) 290-0058 http://www.EMSL.com / manhattanlab@emsl.com

## Test Report: Asbestos Analysis of Bulk Material

	Analyzed				
Test	Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 30-01		Description	207 KITCHEN - SELF	STICK FLOOR TILE	
031900714-	0044	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Brown		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Brown		100.00% Other	None Detected
Sample ID 30-02		Description	207 KITCHEN - SELF	STICK FLOOR TILE	
031900714-	0045	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB Final Residue <1% of ori	01/14/2019 ginal subsample	Brown		100.00% Other	Inconclusive: None Detected
EM NYS 198.4 NOB	01/15/2019	Brown		100.00% Other	None Detected
Sample ID 31-01		Description	208 BATH BOTTOM	LAYER - FLOORING	
031900714-	0046	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Black	None	100.00% Other	Inconclusive : <1.00% Chrysotile
TEM NYS 198.4 NOB	01/15/2019	Black	None	100.00% Other	<1.00% Chrysotile
Sample ID 31-02		Description	208 BATH TOP LAYE	R - FLOORING	
031900714-	0047	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	White		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	White	None	100.00% Other	<1.00% Chrysotile
Sample ID 32-01		Description	209 KITCHEN BOTTO	OM LAYER - FLOOR TILE	
031900714-	0048	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	White		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	White		100.00% Other	None Detected
Sample ID 32-02		Description	209 KITCHEN TOP L	AYER - FLOOR TILE	
031900714-	0049	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	White/ Black		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	White/ Black		100.00% Other	None Detected



307 West 38th Street New York, NY 10018 Tel/Fax: (212) 290-0051 / (212) 290-0058 http://www.EMSL.com / manhattanlab@emsl.com EMSL Order: 031900714 Customer ID: ALPI50 Customer PO: Project ID:

## Test Report: Asbestos Analysis of Bulk Material

	Analyzed	Non-Asbestos			
Test	Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 33-01		Description	UNIT 1 - CARPET MASTIC		
031900714-	0050	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Yellow		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Yellow		100.00% Other	None Detected
Sample ID 33-02		Description	UNIT 2 - CARPET MASTIC		
031900714-	0051	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Yellow		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Yellow		100.00% Other	None Detected
Sample ID 34-01		Description	UNIT 1 KITCHEN - COVEBA	SE & MASTIC	
031900714-	0052	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Brown		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Brown		100.00% Other	None Detected
Sample ID 34-01-Mas	tic	Description	UNIT 1 KITCHEN - COVEBA	SE & MASTIC	
031900714-	0052A	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Yellow		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Yellow	None	100.00% Other	<1.00% Chrysotile
Sample ID 34-02		Description	201 - COVEBASE & MASTIC	;	
031900714-	0053	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB Final Residue <1% of ori	01/14/2019 ginal subsample	Black		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Black		100.00% Other	None Detected
Sample ID 34-02-Mas	tic	Description	201 - COVEBASE & MASTIC	;	
031900714-	0053A	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	White		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	White		100.00% Other	None Detected



307 West 38th Street New York, NY 10018 Tel/Fax: (212) 290-0051 / (212) 290-0058 http://www.EMSL.com / manhattanlab@emsl.com

# Test Report: Asbestos Analysis of Bulk Material

	Analyzed	Non-Asbestos			
Test	Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 35-01		Description	UNIT 1 BATH - PLASTIC	WALL TILE ADHESIVE	
031900714-	0054	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Brown		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Brown		100.00% Other	None Detected
Sample ID 35-02		Description	206 BATH - PLASTIC WA	ALL TILE ADHESIVE	
031900714-	0055	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	White		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	White		100.00% Other	None Detected
Sample ID 36-01		Description	UNIT 1 BATH - SHOWEF	RADHESIVE	
031900714-	0056	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Brown		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Brown		100.00% Other	None Detected
Sample ID 36-02		Description	UNIT 1 BATH - SHOWEF	RADHESIVE	
031900714-	0057	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Brown		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Brown		100.00% Other	None Detected
Sample ID 37-01		Description	BASEMENT FLOOR IN F	ROLL - BLACK MEMBRANE	
031900714-	0058	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Black		100.00% Other	Inconclusive: None Detected
Final Residue <1% of ori	ginal subsample				
TEM NYS 198.4 NOB	01/15/2019	Black		100.00% Other	None Detected
Sample ID 37-02		Description		ROLL - BLACK MEMBRANE	
031900714-	0059	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Black		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Black		100.00% Other	None Detected



307 West 38th Street New York, NY 10018 Tel/Fax: (212) 290-0051 / (212) 290-0058 http://www.EMSL.com / manhattanlab@emsl.com EMSL Order: 031900714 Customer ID: ALPI50 Customer PO: Project ID:

## Test Report: Asbestos Analysis of Bulk Material

	Analyzed			Non-Asbestos	
Test	Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 38-01		Description	203 KITCHEN - SINK	INSULATION	
031900714-	0060	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Black	None	97.00% Other	3.00% Chrysotile
TEM NYS 198.4 NOB	01/14/2019				Positive Stop (Not Analyzed)
Sample ID 38-02		Description	203 KITCHEN - SINK	INSULATION	
031900714-	0061	Homogeneity			
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019				Positive Stop (Not Analyzed)
TEM NYS 198.4 NOB	01/14/2019				Positive Stop (Not Analyzed)
Sample ID 39-01		Description	BASEMENT ON WAL	LS - TAR PAPER	
031900714-	0062	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Black	None	100.00% Other	Inconclusive : <1.00% Chrysotile
TEM NYS 198.4 NOB	01/16/2019	Black	None	100.00% Other	<1.00% Chrysotile
Sample ID 39-02		Description	BASEMENT ON WAL	LS - TAR PAPER	
031900714-	0063	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Black	None	100.00% Other	Inconclusive : <1.00% Chrysotile
TEM NYS 198.4 NOB	01/16/2019	Black		100.00% Other	None Detected
Sample ID 40-01		Description	3RD FLOOR - WIRE	INSULATION	
031900714-	0064	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Black		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Black		100.00% Other	None Detected
Sample ID 40-02		Description	3RD FLOOR - WIRE	INSULATION	
031900714-	0065	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Black		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Black		100.00% Other	None Detected



Tel/Fax: (212) 290-0051 / (212) 290-0058

http://www.EMSL.com / manhattanlab@emsl.com

# Test Report: Asbestos Analysis of Bulk Material

Analyzed			No		
Test	Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 41-01		Description	EXTERIOR - WINDOW	GLAZING	
031900714-0	066	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Brown/ White		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Brown/ White		100.00% Other	None Detected
Sample ID 41-02		Description	EXTERIOR - WINDOW	GLAZING	
031900714-0	067	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	01/14/2019	Brown/ White		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	01/15/2019	Brown/ White		100.00% Other	None Detected

EMSL Analytical, Inc. 307 West 38th Street New York, NY 10018 Tel/Fax: (212) 290-0051 / (212) 290-0058 http://www.EMSL.com / manhattanlab@emsl.com EMSL Order: 031900714 Customer ID: ALPI50 Customer PO: Project ID:

## Test Report: Asbestos Analysis of Bulk Material

The samples in this report were submitted to EMSL for analysis by Asbestos Analysis of Bulk Materials via NYS ELAP Approved Methods. The reference number for these samples is the EMSL Order ID above. Please use this reference number when calling about these samples.

#### Report Comments:

Sample Receipt Date: 1/12/2019 Analysis Completed Date: 1/14/2019

Analyst(s):

Angelica Aquino PLM NYS 198.6 NOB (67)

Venisha Lazarus-Barnes TEM NYS 198.4 NOB (49)

Samples reviewed and approved by:

Sample Receipt Time: 11:17 AM Analysis Completed Time: 9:16 PM

Muhsin Parson TEM NYS 198.4 NOB (2)

ames PAIN

James Hall, Laboratory Manager or Other Approved Signatory

NOB = Non Friable Organically Bound N/A = Not Applicable VCM = Vermiculite Containing Material

-In New York State, TEM is currently the only method that can be used to determine if NOB materials can be considered or treated as non -asbestos containing. All samples examined for the presence of vermiculite when analyzed via NYS 198.1.

-NYS Guidelines for Vermiculite containing samples are available at http://www.wadsworth.org/labcert/elapcert/forms/VermiculiteInterimGuidance\_Rev070913.pdf EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples were received in good condition unless otherwise noted.

This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. This report may contain data that is not covered by the NVLAP accreditation.

Samples analyzed by EMSL Analytical, Inc. New York, NY NYS ELAP 11506

31900714

OrderID: \_031900714 services, Inc. 438 New Karner Road Albany, NY 12205

#### **CHAIN OF CUSTODY**

Client: Alpine Environmental Services, Inc.

438 New Karner Road Albany, NY 12205

Contact: Paul Van Zandt

Phone/Email: 518 250-4047 paulv@alpineenv.com

Turnaround Time: 72Hr

	-	1.1.7
Project: 20 Lake St, Richfield Springs, NY	T	1
Project Number: 18-23711-A		C Se
Sampled By: P. Van Zandt	3.20	N. P.
Date / Time Collected: 01/10/18		Capt.
Delivery: Fed Ex 7741 7004 5933		1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-
	7	35
	Project: <u>20 Lake St, Richfield Springs, NY</u> Project Number: <u>18-23711-A</u> Sampled By: <u>P. Van Zandt</u>	Project: 20 Lake St, Richfield Springs, NY Project Number: 18-23711-A Sampled By: P. Van Zandt Date / Time Collected: 01/10/18

Log No.	Sample No.	Sample Location	Sample Material	Analysis Performed	Notes
	11M-01	203 Kitchen Backsplash	Wall Tile Adhesive	NYS Protocol	Stop at 1 <sup>st</sup> Positive
	11M-02	203 Kitchen Backsplash	Wall Tile Adhesive	EM	11M-01 to 11M-02
	12M-01	204 Bath	Wall Tile Adhesive		Stop at 1 <sup>st</sup> Positive
	12M-02	204 Bath	Wall Tile Adhesive		12M-01 to 12M-02
	13M-01	Basement	Floor Tile Mastic		Stop at 1 <sup>st</sup> Positive
	13-01	Basement	9"x9" Floor Tile		13M-01 to 13-01
	13M-02	Basement	Floor Tile Mastic		Stop at 1 <sup>st</sup> Positive
	13-02	Basement	9"x9" Floor Tile		13M-02 to 13-02
	14M-01	Unit 3 Kitchen	Floor Tile Mastic		Stop at 1 <sup>st</sup> Positive
1-61	14-01	Unit 3 Kitchen	9"x9" Floor Tile		14M-01 to 14-02
	14M-02	Unit 3 Kitchen	Floor Tile Mastic	] [	Stop at 1 <sup>st</sup> Positive
	14-02	Unit 3 Kitchen	9"x9" Floor Tile	] [	14M-02 to 14-02

Disposition of Samples: Accept\_\_\_\_\_ Reject\_\_\_\_ Explain\_\_\_\_ Comments:

Relinquished By:	Received By:	Date:	Time:
PUV=246	luno	1/12/14	7 11:17 AM
20		( (	

Page 1 of 6

OrderID: 031900714 services, Inc. 438 New Karner Road Albany, NY 12205

## 031900714

#### **CHAIN OF CUSTODY**

Client: Alpine Environmental Services, Inc.

438 New Karner Road

Albany, NY 12205

Contact: Paul Van Zandt

Phone/Email: 518 250-4047 paulv@alpineenv.com

Turnaround Time: 72Hr

Project: 20 Lake St, Richfield Springs, NY		E D
Project Number: 18-23711-A	0	3
Sampled By: P. Van Zandt	MM	2005
Date / Time Collected: 01/10/18	N	0
Delivery: Fed Ex 7741 7004 5933	27	33
	-	Cit.
		1

Log No.	Sample No.	Sample Location	Sample Material	Analysis Performed	Notes 😡
	15-01	Unit 1 Kitchen	12"x12" Floor Tile	NYS Protocol	Stop at 1 <sup>st</sup> Positive
	15-02	Unit 1 Kitchen	12"x12" Floor Tile		15-01 to 15-02
-	16-01	Unit 1 Bath	Floor Tile		Stop at 1 <sup>st</sup> Positive
	16-02	Unit 1 Kitchen Countertop	Floor Tile		16-01 to 16-02
24	17-01	Unit 2 Entry	12"x12" Floor Tile & Mastic		Stop at 1 <sup>st</sup> Positive
a side of S	17-02	Unit 2 Kitchen	12"x12" Floor Tile & Mastic		17-01 to 17-02
	18-01	Unit 2 Living Room	Self Stick Floor Tile		Stop at 1 <sup>st</sup> Positive
	18-02	Unit 2 Living Room	Self Stick Floor Tile		18-01 to 18-02
	19-01	Unit 3 Bath	Self Stick Floor Tile		Stop at 1 <sup>st</sup> Positive
	19-02	Unit 3 Bath	Self Stick Floor Tile		19-01 to 19-02
	20-01	200 Kitchen Bottom Layer	Floor Tile		Stop at 1 <sup>st</sup> Positive
	20-02	200 Kitchen Middle Layer	Floor Tile		20-01 to 20-03

Disposition of Samples: Accept\_\_\_\_ Reject\_\_\_\_ Explain\_ Comments:

Pelvezes and		
Tave and quino	1/12/19	? 11:17Am
	1 1	
Page 2 of 6	Zan	1/15/

6

Page 2 Of

031900714

OrderID: 031900714 Appine Environmental services, Inc. 438 New Karner Road Albany<sup>\*</sup>, NY 12205

**CHAIN OF CUSTODY** 

Client: Alpine Environmental Services, Inc.

438 New Karner Road

Albany, NY 12205

Contact: Paul Van Zandt

Phone/Email: 518 250-4047 paulv@alpineenv.com

Turnaround Time: 72Hr

	And and a second second	
Project: 20 Lake St, Richfield Springs, NY	1	R
Project Number: 18-23711-A	ru ru	822 1975
Sampled By: P. Van Zandt	2.5	Nº.
Date / Time Collected: 01/10/18		Sand Line Second Second
Delivery: Fed Ex 7741 7004 5933	0	5
		2.00

Log No.	Sample No.	Sample Location	Sample Material	Analysis Performed	Notes
	20-03	200 Kitchen Top Layer	Floor Tile	NYS Protocol	
	21-01	200 Bath Bottom Layer	Floor Tile		Stop at 1 <sup>st</sup> Positive
	21-02	200 Bath Top Layer	Floor Tile		21-01 to 21-02
150	22-01	201 Closet	Linoleum		Stop at 1 <sup>st</sup> Positive
	22-02	201 Closet	Linoleum		22-01 to 22-02
	23-01	202	Self Stick Floor Tile		Stop at 1 <sup>st</sup> Positive
	23-02	202	Self Stick Floor Tile		23-01 to 23-02
	24-01	203 Kitchen	Linoleum		Stop at 1 <sup>st</sup> Positive
	24-02	203 Kitchen	Linoleum		24-01 to 24-02
	25-01	204 Bath Bottom Layer	Flooring		Stop at 1 <sup>st</sup> Positive
	25-02	204 Bath Top Layer	Flooring		25-01 to 25-02
	26-01	204 Closet	Linoleum		Stop at 1 <sup>st</sup> Positive

Comments:

Relinquished By:	Received By:	Date:	Time:
PUV=246	Quiño	1/12/19	11:17 m
		/ / · ·	
D 2 66			

Page 3 of 6

Page 3 Of 6

1/157

031900914

OrderID: 031900714 Applie Environmental Services, Inc. 438 New Karner Road Albany, NY 12205

### **CHAIN OF CUSTODY**

<u>CHAIN</u>	<b>DF CUSTODY</b>	0	7.5
Client: Alpine Environmental Services, Inc.	Project: 20 Lake St, Richfield Springs, NY	5	F
438 New Karner Road	Project Number: 18-23711-A	1	EP
Albany, NY 12205	Sampled By: P. Van Zandt	N	THE .
Contact: Paul Van Zandt	Date / Time Collected: 01/10/18		0
Phone/Email: 518 250-4047 paulv@alpineenv.com	Delivery: Fed Ex 7741 7004 5933		12
Turnaround Time: 72Hr		0	T.C.

Log No.	Sample No.	Sample Location	Sample Material	Analysis Performed	Notes	
	26-02	204 Closet	Linoleum	NYS Protocol	26-01 to 26-02	
192 192	27-01	205 Kitchen	12"x12" Floor Tile & Mastic		Stop at 1 <sup>st</sup> Positive	6
	27-02	205 Kitchen	12"x12" Floor Tile & Mastic		27-01 to 27-02	
	28-01	205 Hall Bottom Layer	Flooring		Stop at 1 <sup>st</sup> Positive	
19	28-02	205 Hall Top Layer	Flooring		28-01 to 28-02	
ANE 19 7	29-01	207 Hall Bottom Layer	Flooring		Stop at 1 <sup>st</sup> Positive	
	29-02	207 Hall Top Layer	Flooring		29-01 to 29-02	
	30-01	207 Kitchen	Self Stick Floor Tile		Stop at 1 <sup>st</sup> Positive	
	30-02	207 Kitchen	Self Stick Floor Tile		30-01 to 30-02	
	31-01	208 Bath Bottom Layer	Flooring		Stop at 1 <sup>st</sup> Positive	
	31-02	208 Bath Top Layer	Flooring		31-01 to 31-02	
	32-01	209 Kitchen Bottom Layer	Floor Tile		Stop at 1 <sup>st</sup> Positive	

Comments:

ime:	Date:		Received By:	elinquished By:
1:17AW	1/12/19	unio,		PIVEZ6
,				
19	1/157			Page 4 of 6
10	1/157	R		Page 4 of 6

Page 4 Of 6

		0		-	
$\cap$	0	(1)	nn	71	1
	n	91	11	11	4
U	11	1	10	11	1

OrderID: \_031900714 services, Inc. 438 New Karner Road Albany, NY 12205

#### **CHAIN OF CUSTODY**

Client: Alpine Environmental Services, Inc.

438 New Karner Road Albany, NY 12205

Contact: Paul Van Zandt

Phone/Email: 518 250-4047 paulv@alpineenv.com Delivery: Fed Ex 7741 7004 5933

Turnaround Time: 72Hr

 Project: 20 Lake St, Richfield Springs, NY

 Project Number: 18-23711-A

 Sampled By: P. Van Zandt

 Date / Time Collected: 01/10/18

 Delivery: Fed Ex 7741 7004 5933

Log No.	Sample No.	Sample Location	Sample Material	Analysis Performed	Notes
	32-02	209 Kitchen Top Layer	Floor Tile	NYS Protocol	32-01 to 32-02
6	33-01	Unit 1	Carpet Mastic		Stop at 1 <sup>st</sup> Positive
	33-02	Unit 2	Carpet Mastic		33-01 to 33-02
	34-01	Unit 1 Kitchen	Covebase & Mastic		Stop at 1 <sup>st</sup> Positive
	34-02	201	Covebase & Mastic		34-01 to 34-02
8 3 A 12 A	35-01	Unit 1 Bath	Plastic Wall Tile Adhesive		Stop at 1 <sup>st</sup> Positive
a statute	35-02	206 Bath	Plastic Wall Tile Adhesive		35-01 to 35-02
- 55, 7	36-01	Unit 1 Bath	Shower Adhesive		Stop at 1 <sup>st</sup> Positive
	36-02	Unit 1 Bath	Shower Adhesive		36-01 to 36-02
	37-01	Basement Floor in Roll	Black Membrane		Stop at 1 <sup>st</sup> Positive
	37-02	Basement Floor in Roll	Black Membrane		37-01 to 37-02
	38-01	203 Kitchen	Sink Insulation		Stop at 1 <sup>st</sup> Positive

Disposition of Samples: Accept\_\_\_\_ Reject\_\_\_ Explain\_\_ Comments:

Received By:		Time:
Juno	1/12/19	11:19AM
/-0		
	Junio	Junio 1/12/19

6

Page 5 Of

an

1-15-19

Page 5 of 6

OrderID: 031900714 services, Inc.
438 New Karner Road
Albany, NY 12205

ũ

#### **CHAIN OF CUSTODY**

Client: Alpine Environmental Services, Inc.

438 New Karner Road

Albany, NY 12205

Contact: Paul Van Zandt

Phone/Email: 518 250-4047 paulv@alpineenv.com

Turnaround Time: 72Hr

or courobr		- and the second
Project: 20 Lake St, Richfield Spr	ings, NY	10
Project Number: 18-23711-A	AN R	T
Sampled By: P. Van Zandt	12	E
Date / Time Collected: 01/10/18	AN AN	£1
Delivery: Fed Ex 7741 7004 5933		14
		1

Log No.	Sample No.	Sample Location	Sample Material	Analysis Performed	Notes
	38-02	203 Kitchen	Sink Insulation	NYS Protocol	38-01 to 38-02
	39-01	Basement on Walls	Tar Paper		Stop at 1 <sup>st</sup> Positive
	39-02	Basement on Walls	Tar Paper		39-01 to 39-02
	40-01	3 <sup>rd</sup> Floor	Wire Insulation		Stop at 1 <sup>st</sup> Positive
	40-02	3 <sup>rd</sup> Floor	Wire Insulation		40-01 to 40-02
	41-01	Exterior	Window Glazing		Stop at 1 <sup>st</sup> Positive
	41-02	Exterior	Window Glazing		41-01 to 41-02
Man					
		1.1			

Disposition of Samples: Accept	Reject	Explain
Comments:		

Relinquished By:	Received By:	Date:	Time:
PIVEZA	> Musto	1/12/19	11:17AW
and the second			
Page 6 of 6		aus	
	Page 6 Of 6	)an- 1-15-19	

Page 6 Of

Customer ID: ALPI50 **Customer PO: Project ID:** 

EMSL Order: 031900854

Phone:	(518) 250-4047
Fax:	
Received Date:	01/15/2019 10:37 AM
Analysis Date:	01/18/2019
Collected Date:	01/14/2019

Project: 18-23711-A/ 20 LAKE ST/ RICHFIELD SPRINGS, NY

Albany, NY 12205

#### Test Report: Asbestos Analysis of Bulk Material

		Analyzed		N	on-Asbestos	
Т	est	Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID	42-01		Description	SIDE PORCH ROOF B	OTTOM LAYER - SHINGLE	
	031900854-0	0001	Homogeneity	Heterogeneous		
PLM NYS 1	98.1 Friable					Not Analyzed
PLM NYS 1	98.6 VCM					Not Analyzed
PLM NYS 1	98.6 NOB	01/18/2019	Black		100.00% Other	Inconclusive: None Detected
TEM NYS 1	98.4 NOB	01/18/2019	Black		100.00% Other	None Detected
Sample ID	42-02		Description	SIDE PORCH ROOF T	OP LAYER - SHINGLE	
	031900854-0	0002	Homogeneity	Heterogeneous		
PLM NYS 1	98.1 Friable					Not Analyzed
PLM NYS 1	98.6 VCM					Not Analyzed
PLM NYS 1	98.6 NOB	01/18/2019	Black		100.00% Other	Inconclusive: None Detected
TEM NYS 1	98.4 NOB	01/18/2019	Black		100.00% Other	None Detected

EMSL Analytical, Inc. 307 West 38th Street New York, NY 10018 Tel/Fax: (212) 290-0051 / (212) 290-0058 http://www.EMSL.com / manhattanlab@emsl.com EMSL Order: 031900854 Customer ID: ALPI50 Customer PO: Project ID:

#### Test Report: Asbestos Analysis of Bulk Material

The samples in this report were submitted to EMSL for analysis by Asbestos Analysis of Bulk Materials via NYS ELAP Approved Methods. The reference number for these samples is the EMSL Order ID above. Please use this reference number when calling about these samples.

#### Report Comments:

Sample Receipt Date: 1/15/2019 Analysis Completed Date: 1/18/2019 Sample Receipt Time: 10:37 AM Analysis Completed Time: 12:43 AM

Analyst(s):

Angelica Aquino PLM NYS 198.6 NOB (2)

Samples reviewed and approved by:

Venisha Lazarus-Barnes TEM NYS 198.4 NOB (2)

James Hall, Laboratory Manager or Other Approved Signatory

NOB = Non Friable Organically Bound N/A = Not Applicable VCM = Vermiculite Containing Material

-In New York State, TEM is currently the only method that can be used to determine if NOB materials can be considered or treated as non -asbestos containing. All samples examined for the presence of vermiculite when analyzed via NYS 198.1.

-NYS Guidelines for Vermiculite containing samples are available at http://www.wadsworth.org/labcert/elapcert/forms/VermiculiteInterimGuidance\_Rev070913.pdf EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples were received in good condition unless otherwise noted.

This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. This report may contain data that is not covered by the NVLAP accreditation.

Samples analyzed by EMSL Analytical, Inc. New York, NY NYS ELAP 11506

Initial report from: 01/18/2019 12:01:20

OrderID: 031900854 Appine Environmental services, Inc. 438 New Karner Road Albany, NY 12205

Ø31900854

2

#### **CHAIN OF CUSTODY**

Client: Alpine Environmental Services, Inc.

438 New Karner Road

Albany, NY 12205

Contact: Paul Van Zandt

Phone/Email: 518 250-4047 paulv@alpineenv.com Delivery: Fed Ex 7956 6119 8363

Turnaround Time: 72Hr

Project: 20 Lake St, Richfield Springs, NY Project Number: 18-23711-A UI Sampled By: P. Van Zandt Date / Time Collected: 01/14/18 0

Log No.	Sample No.	Sample Location	Sample Material	Analysis Performed	Notes
	42-01	Side Porch Roof Bottom Layer	Shingle	NYS Protocol	Stop at 1 <sup>st</sup> Positive
	42-02	Side Porch Roof Top Layer	Shingle	Carl P.	42-01 to 42-02
	128		· · · · · · · · · ·		
Lades.	. bu				an ann aite
	89 .	-			
		-2×			
					·
				-	
Dispositio		les: Accept Reject E	xplain		

Relinquished By:	Received By:	Date:	Time:
PIVEZA6	Sin	1/15/19	10:2440

Page 1 of 1

73 aug Page 1 Of 1



STREET, STREET

New York State – Department of Labor

Division of Safety and Health License and Certificate Unit State Campus, Building 12 Albany, NY 12240

#### ASBESTOS HANDLING LICENSE

Alpine Environmental Services, Inc.

438 New Karner Road

Albany, NY 12205

FILE NUMBER: 00-0320 LICENSE NUMBER: 29095 LICENSE CLASS: RESTRICTED DATE OF ISSUE: 07/06/2018 EXPIRATION DATE: 07/31/2019

Duly Authorized Representative – Craig Petreikis:

M

This license has been issued in accordance with applicable provisions of Article 30 of the Labor Law of New York State and of the New York State Codes, Rules and Regulations (12 NYCRR Part 56). It is subject to suspension or revocation for a (1) serious violation of state, federal or local laws with regard to the conduct of an asbestos project, or (2) demonstrated lack of responsibility in the conduct of any job involving asbestos or asbestos material.

This license is valid only for the contractor named above and this license or a photocopy must be prominently displayed at the asbestos project worksite. This license verifies that all persons employed by the licensee on an asbestos project in New York State have been issued an Asbestos Certificate, appropriate for the type of work they perform, by the New York State Department of Labor.

SH 432 (8/12)

Eileen M. Franko, Director For the Commissioner of Labor

#### NEW YORK STATE DEPARTMENT OF HEALTH WADSWORTH CENTER



Expires 12:01 AM April 01, 2019 Issued April 01, 2018

#### CERTIFICATE OF APPROVAL FOR LABORATORY SERVICE Issued in accordance with and pursuant to section 502 Public Health Law of New York State

NY Lab Id No: 11506

MR. JAMES HALL EMSL ANALYTICAL, INC 307 WEST 38TH STREET SUITE 901 NEW YORK, NY 10018

> is hereby APPROVED as an Environmental Laboratory for the category ENVIRONMENTAL ANALYSES SOLID AND HAZARDOUS WASTE All approved subcategories and/or analytes are listed below:

#### Miscellaneous

Asbestos in Friable Material	Item 198.1 of Manual
	EPA 600/M4/82/020
Asbestos in Non-Friable Material-PLM	Item 198.6 of Manual (NOB by PLM)
Asbestos in Non-Friable Material-TEM	Item 198.4 of Manual
Asbestos-Vermiculite-Containing Material	Item 198.8 of Manual
Lead in Dust Wipes	EPA 7000B
Lead in Paint	EPA 7000B

Sample Preparation Methods

EPA 3051A

#### Serial No.: 57819

Property of the New York State Department of Health. Certificates are valid only at the address shown, must be conspicuously posted, and are printed on secure paper. Continued accreditation depends on successful ongoing participation in the Program. Consumers are urged to call (518) 485-5570 to verify the laboratory's accreditation status.