

A2Z Environmental LLC

Asbestos License #73261—Asbestos Certification # 92-09664

P.O. Box 188
Pulaski, New York 13142
(315)527-8888

ASBESTOS BUILDING INSPECTION REPORT PRE-DEMOLITION BUILDING SURVEY

PERFORMED FOR:

Greater Mohawk Valley Land Bank, Inc.

500 East Main Street - Suite 2A

Little Falls, New York 13365

PROJECT SITE:

Greater Mohawk Valley Land Bank, Inc.

76-78 Furnace Street

Little Falls, **New York**

1 2

1 9

1 8

A2Z Environmental LLC

Asbestos License #73261---Asbestos Certification # 92-09664

P.O. Box 188
Pulaski, New York 13142
(315)527-8888

CONTENTS

1.0	EXECUTIVE SUMMARY _____	1
2.0	INTRODUCTION _____	1
3.0	BACKGROUND _____	1
4.0	METHODOLOGY _____	2
5.0	SUMMARY OF FINDINGS _____	3
6.0	RESPONSIBILITY OF OWNER OR OWNERS AGENT _____	3
7.0	ASBESTOS CONTROL BUREAU DISTRICT OFFICES _____	4

List of Tables

Table 5.1 -Materials analyzed and found to be ACM

Asbestos Bulk Sample Summary _____	5
------------------------------------	---

Appendices

Appendix A	Certifications and License
Appendix B	Floor Plan Drawings and Pictures
Appendix C	Laboratory Analysis Reports and Chain of Custody
Appendix D	Laboratory License and Certificates

A2Z Environmental LLC

Asbestos License #73261—Asbestos Certification # 92-09664

P.O. Box 188
Pulaski, New York 13142
(315)527-8888

1.0 EXECUTIVE SUMMARY

A2Z Environmental llc. was retained by Greater Mohawk Valley Land Bank, Inc. to perform a limited pre-demolition building survey for asbestos containing materials (ACM). This report is not to be used for design purposes. Measurements are for a guide and should be verified by abatement contractor. There may be areas that were inaccessible for the inspector to sample.

The survey was performed by Kyle Roberts, New York State certified building inspector (certificate Number 92-09664) for A2Z Environmental llc. and included the following:

- Review of available building records for reference to ACM;
- Visual inspection of the area to identify suspect ACM;
- Collection of representative samples of suspect ACM;
- Analysis of all samples by an independent, accredited laboratory;
- Preparation of a written report.

Fieldwork for the survey was performed on 12-10-2018. Samples were delivered to EMSL Analytical INC. for polarized light microscopy (PLM) or (TEM) analysis on 12-14-2018. The survey included the collection and analysis of 58 samples.

2.0 INTRODUCTION

The survey was performed at the request of Greater Mohawk Valley Land Bank, Inc. in preparation for possible demolition or renovation of the four family apartment house located at 76-78 Furnace Street. The objective of the survey was to identify ACM within the space or the entire building so that appropriate considerations can be made prior to demolition of the building or renovation of the said space.

New York State Department of Labor Industrial Code Rule 56 (12NYCRR, Part 56) requires that prior to advertising for bids or contracting for or commencing work on any demolition work on a building, that the owner or agent of such building shall cause a survey for ACM to be conducted, and that identified ACM be removed by a licensed contractor prior to initiation of demolition activities. This survey was performed in accordance with these requirements.

3.0 BACKGROUND

There are many factors that must be considered when determining the extent of potential health risks associated with the presence of asbestos-containing materials (ACM) in buildings. The major concern is with the possibility of fiber release from the ACM and the subsequent inhalation of these fibers by building occupants.

A2Z Environmental LLC

Asbestos License #73261---Asbestos Certification # 92-09664

P.O. Box 188
Pulaski, New York 13142
(315)527-8888

Asbestos is a known carcinogen found in many types of building materials, but its presence alone may not constitute a health hazard. Rather, a health hazard occurs when the asbestos fibers are in some way disturbed and become airborne. Asbestos fibers are most likely to be released into the air when the materials in which they are contained become loose, friable, or otherwise show signs of damage or deterioration by various causal agents.

Inhalation of these microscopic asbestos fibers has been medically proven to cause chronic disease such as asbestosis, mesothelioma and lung cancer. The severity of these diseases, along with the discovery of great amounts of asbestos in public and private buildings, has led government agencies to promulgate regulations aimed at reducing asbestos exposure. Maximum allowable exposure levels have been set for building occupants, and methods of compliance for removal and disposal of ACM have been instituted. Therefore, it is necessary to locate and identify all ACM within a building. Comprehensive data to this effect will allow for the implementation of a systematic asbestos abatement program.

4.0 METHODOLOGY

The bulk sampling procedure utilized by A2Z Environmental LLC. is designed to collect samples of materials suspected to contain asbestos. Each individual type of materials as delineated by color, texture, pattern and location will be referred to as a homogeneous sampling area. Each homogeneous area will be sampled and assessed independently of each other.

The procedure for collecting a bulk sample entails complete penetration and removal of all layers of the suspect material, while at the same time, minimizing damage and potential fiber release. The sampling procedure begins with complete wetting of the sampling area. A core section is then cut from the material and placed in a sealed, air-tight sample container. The exposed area is then sealed with spray adhesive and patched with duct tape when in an occupied space. The area where the core sample was removed is then labeled with a sample number to facilitate future reference. The sampling tool is then wet wiped and decontaminated with a disposable towel.

Each labeled sample is then transported along with a chain of custody form to a certified laboratory for analysis. Laboratory analysis of friable samples (materials which are able to be crushed or reduced to powder by hand pressure) is performed using Polarized Light Microscopy with Dispersion Staining in accordance with the EPA Interim Method for the Determination of Asbestos in Bulk Insulation Samples (EPA - 600/M4-82-020).

A2Z Environmental LLC

Asbestos License #73261—Asbestos Certification # 92-09664

P.O. Box 188
Pulaski, New York 13142
(315)527-8888

Non-friable organically bound samples (NOBs) such as floor tile and roofing undergo gravimetric reduction and are then analyzed using (PLM) polarized light microscopy. Samples that test positive for asbestos are reported as such. Samples which test negative for asbestos (less than 1 % asbestos by weight) must be further analyzed by (TEM) transmission electron microscopy.

The testing laboratory is approved under the NYS Department of Health - Environmental Laboratory Approval Program (ELAP) as well as the National Institute of Standards and Technology - National Voluntary Laboratory Approval Program (NVLAP).

5.0 SUMMARY OF FINDINGS

There were no building records available at the time of the survey, therefore building records have have not, been reviewed as part of this effort.

The laboratory visually inspected for the presence of suspect ACM on 12 - 19 - 2018 & - -

See Table 5.1 (starting on page 5) for a complete list of samples collected. If any additional suspect materials are discovered prior to or during demolition activities, then the material must be assumed to be asbestos-containing or must undergo Laboratory analysis in accordance with 29 CFR 191.0.1.1.01 to prove it non-asbestos.

**** SEE APPENDIX B FOR LOCATIONS OF ACM ****

It must be noted that the quantities of ACM provided on table 5.1 are estimates of the actual materials present that were available for inspection and assessment. These figures themselves should not be used as the sole basis for asbestos abatement contractors' bids or cost estimates. They are meant merely as estimates to gauge the scope of the project.

The purpose of the inspection was to determine the extent of asbestos-containing materials associated with the above referenced property only. New York State Department of Labor Regulations, 12 NYCRR Part 56, requires removal of all asbestos-containing materials from a building or structure prior to demolition or renovation activities.

Details concerning ACM location and quantity, sample locations, laboratory analysis, and consultant credentials are included in this report.

6.0 Responsibility of owner or owner agent

The owner or owners agent is required to send a copy of this report to the Department of Labor prior to any Asbestos Abatement. The address that the report needs to be sent to depends on the county that the property is located. The addresses for the different Department of Labor District offices are listed on page 4 of this report.

A2Z Environmental LLC

Asbestos License #73261—Asbestos Certification # 92-09664

P.O. Box 188
Pulaski, New York 13142
(315)527-8888

7.0 ASBESTOS CONTROL BUREAU DISTRICT OFFICES

ALBANY DISTRICT:

Counties - Albany, Clinton, Columbia, Dutchess, Essex, Fulton, Green, Montgomery, Orange, Putnam, Rockland, Rensselaer, Saratoga, Schenectady, Schoharie, Sullivan, Ulster, Warren, Washington

State Office Campus, Room 157, Albany, NY 12240
(518) 457-1255 (FAX) (518) 485-8054
(518) 457-2072 (FAX)(518) 485-8054 (Field Office)

BUFFALO DISTRICT:

Counties - Cattaraugus, Chautauqua, Erie, Genesee, Livingston, Monroe, Niagara, Ontario, Orleans, Wayne, Wyoming, Yates

65 Court Street, Rm. 405, Buffalo, NY 14202
(716) 847-7601 (716) 847-7126 (FAX) (716) 847-7138

NEW YORK CITY DISTRICT:

Counties - Bronx, Kings, Nassau, New York, Queens, Richmond, Suffolk, Westchester

One Hudson Square, 75 Varick Street (7th Floor), New York, NY 10013
(212) 775-3532

SYRACUSE DISTRICT:

Counties - Allegany, Broome, Cayuga, Chemung, Chenango, Cortland, Delaware, Franklin, Hamilton, Herkimer, Jefferson, Lewis, Madison, Oneida, Onondaga, Oswego, Otsego, St. Lawrence, Schuyler, Seneca, Steuben, Tioga, Tompkins,

450 S. Salina Street, Syracuse, NY 13202
(315) 479-3215 (FAX) (315) 479-3333

A2Z Environmental LLC

Asbestos License #73261—Asbestos Certification # 92-09664

P.O. Box 188
Pulaski, New York 13142
(315)527-8888

Appendix A

Certification and License

New York State – Department of Labor

Division of Safety and Health
License and Certificate Unit
State Campus, Building 12
Albany, NY 12240

ASBESTOS HANDLING LICENSE

A 2 Z Environmental LLC

P.O. Box 188

Pulaski, NY 13142

FILE NUMBER: 13-73261
LICENSE NUMBER: 73261
LICENSE CLASS: RESTRICTED
DATE OF ISSUE: 10/10/2018
EXPIRATION DATE: 10/31/2019

Duly Authorized Representative – Jamie D Foster:

This license has been issued in accordance with applicable provisions of Article 30 of the Labor Law of New York State and of the New York State Codes, Rules and Regulations (12 NYCRR Part 56). It is subject to suspension or revocation for a (1) serious violation of state, federal or local laws with regard to the conduct of an asbestos project, or (2) demonstrated lack of responsibility in the conduct of any job involving asbestos or asbestos material.

This license is valid only for the contractor named above and this license or a photocopy must be prominently displayed at the asbestos project worksite. This license verifies that all persons employed by the licensee on an asbestos project in New York State have been issued an Asbestos Certificate, appropriate for the type of work they perform, by the New York State Department of Labor.



Eileen M. Franko, Director
For the Commissioner of Labor

STATE OF NEW YORK - DEPARTMENT OF LABOR
ASBESTOS CERTIFICATE

N.Y.S.



KYLE E ROBERTS
CLASS(EXPIRES)
A HAND(01/19) D INSP(01/19)

CERT# 09-13240
DMV# 869886745

MUST BE CARRIED ON ASBESTOS PROJECTS



01213 004629685 10

EYES BRO
HAIR BRO
HGT 5' 10"

IF FOUND RETURN TO:
NYS DOL - L&C UNIT
ROOM 161A BUILDING 12
STATE OFFICE CAMPUS
ALBANY NY 12240

New York State Department of Health Certificate of Asbestos Safety Training

This form is the official record of successful completion of a New York State accredited asbestos safety training course.

Certificate No. **808706**

I - To be completed by Trainee

Name of Trainee (print) KYLE ROBERTS		NYS Depart. of Motor Vehicles ID (DMV ID) ¹ 669 886 545	
Signature of Trainee <i>[Signature]</i>		Telephone Number 315-527-5150	Date of Birth ¹ 01-06-1986
Address 124 WESTMORELAND ST. WHITESBORO, NY 13492			
(Street or PO Box)		(City)	(State) (Zip Code)

II - To be completed by Training Sponsor

Provider's Name Cornerstone Training Institute		Telephone Number 585-319-3625	
Address 460 State Street, 2nd Floor Rochester, NY 14608		Course Location: 460 State Street Rochester, NY 14608	

Course Title: Inspector Initial Refresher NYS DOH use only DOH Equivalency²

Training Language: English Other: _____ Exam Grade/Date: 96% 3/28/18

Dates of Training: From: 3/26/18 To: 3/28/18 Expires: 3/28/19

I certify that the asbestos safety training course given on the above date complied with both 10 NYCRR Part 73 and TSCA Title II, was consistent with the curriculum and instructors approved by the New York State Department of Health, and the trainee receiving this certificate completed the training course and successfully passed the examination.

Training Director²: [Signature] (Print) [Signature] (Signature) **STUDENT**

A2Z Environmental LLC

Asbestos License #73261---Asbestos Certification # 92-09664

P.O. Box 188
Pulaski, New York 13142
(315)527-8888

Appendix B

Floor Plan Drawings and Pictures



A2Z Environmental LLC

Asbestos License #73261---Asbestos Certification # 92-09664

P.O. Box 188
Pulaski, New York 13142
(315)527-8888

Appendix C

Laboratory Analysis Reports and Chain of Custody



EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018
Tel/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order: 031833575
Customer ID: AZCC25
Customer PO:
Project ID:

Attention: Jamie Foster
A2Z Environmental LLC.
PO Box 188
Pulaski, NY 13142

Phone: (315) 527-8888
Fax: (315) 363-4525
Received Date: 12/14/2018 1:27 PM
Analysis Date: 12/19/2018
Collected Date: 12/10/2018

Project: A2Z12122018B/ 76-78 FURNACE STREET, LITTLE FALLS

Test Report:Asbestos Analysis of Bulk Material

Test	Analyzed Date	Color	Non-Asbestos		Asbestos
			Fibrous	Non-Fibrous	
Sample ID 01-1A 031833575-0001			Description BASEMENT - DUCT WRAP Homogeneity Heterogeneous		
PLM NYS 198.1 Friable	12/19/2018	Gray	None	50.00% Non-fibrous (other)	50.00% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 02-1B 031833575-0002			Description BASEMENT - DUCT WRAP Homogeneity		
PLM NYS 198.1 Friable	12/19/2018				Positive Stop (Not Analyzed)
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 03-2A 031833575-0003			Description BASEMENT - INSULATION VAPOR BARRIER (PINK) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Brown/ Pink		100.00% Other	None Detected
Sample ID 04-2B 031833575-0004			Description BASEMENT - INSULATION VAPOR BARRIER (PINK) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Brown/ Pink		100.00% Other	None Detected
Sample ID 05-3A 031833575-0005			Description BASEMENT - INSULATION VAPOR BARRIER (YELLOW) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Brown/ Yellow		100.00% Other	None Detected

Initial report from: 12/19/2018 06:08:10



EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018
 Tel/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order: 031833575
Customer ID: AZCC25
Customer PO:
Project ID:

Test Report:Asbestos Analysis of Bulk Material

Test	Analyzed Date	Color	Non-Asbestos		Asbestos
			Fibrous	Non-Fibrous	
Sample ID 06-3B 031833575-0006			Description BASEMENT - INSULATION VAPOR BARRIER (YELLOW)		
			Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Brown/ Yellow		100.00% Other	None Detected
Sample ID 07-4A 031833575-0007			Description 78 1/2 - 1ST FLOOR - FRONT ENTRANCE - FLOOR - 12"X12" SELF STICK TILE (BLACK/ WHITE)		
			Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	White/ Black		100.00% Other	None Detected
Sample ID 08-4B 031833575-0008			Description 76 - 1ST FLOOR - FRONT ENTRANCE - FLOOR - 12"X12" SELF STICK TILE (BLACK/ WHITE)		
			Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	White/ Black		100.00% Other	None Detected
Sample ID 09-5A 031833575-0009			Description 76 - 1ST FLOOR - HALL - FLOOR - V12"X12" SELF STICK TILE (WHITE/ PINK FLOWER)		
			Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	White/ Pink		100.00% Other	None Detected
Sample ID 10-5B 031833575-0010			Description 76 - 1ST FLOOR - HALL - FLOOR - V12"X12" SELF STICK TILE (WHITE/ PINK FLOWER)		
			Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	White/ Pink		100.00% Other	None Detected
Sample ID 11-6A 031833575-0011			Description 78 1/2 - 1ST FLOOR - BATHROOM - JOINT COMPOUND		
			Homogeneity Homogeneous		
PLM NYS 198.1 Friable	12/19/2018	White		60.00% Ca Carbonate 40.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial report from: 12/19/2018 06:08:10



EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018
 Tel/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order: 031833575
Customer ID: AZCC25
Customer PO:
Project ID:

Test Report:Asbestos Analysis of Bulk Material

Test	Analyzed Date	Color	Non-Asbestos		Asbestos
			Fibrous	Non-Fibrous	
Sample ID 12-6B 031833575-0012			Description 76 - 1ST FLOOR - BATHROOM - JOINT COMPOUND Homogeneity Heterogeneous		
PLM NYS 198.1 Friable	12/19/2018	Tan/ White		55.00% Ca Carbonate 45.00% Non-fibrous (other)	None Detected
Inseparable paint / coating layer included in analysis					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 13-6C 031833575-0013			Description 78 1/2 - 1ST FLOOR - BATHROOM - DRYWALL Homogeneity Homogeneous		
PLM NYS 198.1 Friable	12/19/2018	Gray		60.00% Gypsum 40.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 14-6D 031833575-0014			Description 76 - 1ST FLOOR - HALL - DRYWALL Homogeneity Homogeneous		
PLM NYS 198.1 Friable	12/19/2018	Brown/ Gray	18.00% Cellulose	55.00% Gypsum 27.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 15-7A 031833575-0015			Description 76 - 1ST FLOOR - BATHROOM - CEILING - 2'X4' ACOUSTICAL CEILING TILE (SMOOTH) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	White/ Beige		100.00% Other	None Detected
Sample ID 16-7B 031833575-0016			Description 76 - 1ST FLOOR - BATHROOM - CEILING - 2'X4' ACOUSTICAL CEILING TILE (SMOOTH) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	White/ Beige		100.00% Other	None Detected
Sample ID 17-8A 031833575-0017			Description 76 - 1ST FLOOR - KITCHEN - INTERIOR DOOR TRIM - CAULKING Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	White		100.00% Other	None Detected

Initial report from: 12/19/2018 06:08:10



EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018
 Tel/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order: 031833575
Customer ID: AZCC25
Customer PO:
Project ID:

Test Report:Asbestos Analysis of Bulk Material

Test	Analyzed Date	Color	Non-Asbestos		Asbestos
			Fibrous	Non-Fibrous	
Sample ID 18-8B 031833575-0018			Description 78 1/2 - 1ST FLOOR - KITCHEN - INTERIOR DOOR TRIM - CAULKING		
			Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	White		100.00% Other	None Detected
Sample ID 19-9A 031833575-0019			Description 76 - 1ST FLOOR - BATHROOM - FLOOR - LINOLEUM (WHITE)		
			Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	White		100.00% Other	None Detected
Sample ID 20-9B 031833575-0020			Description 76 - 1ST FLOOR - BATHROOM - FLOOR - LINOLEUM (WHITE)		
			Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	White		100.00% Other	None Detected
Sample ID 21-10A 031833575-0021			Description 76 - 1ST FLOOR - BEDROOM BEHIND BATHROOM - PLASTER		
			Homogeneity Homogeneous		
PLM NYS 198.1 Friable	12/19/2018	Brown	None	50.00% Gypsum 17.90% Non-fibrous (other) 30.00% Quartz	2.10% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 22-10B 031833575-0022			Description 78 1/2 -1ST FLOOR - LIVING ROOM - PLASTER		
			Homogeneity		
PLM NYS 198.1 Friable	12/19/2018				Positive Stop (Not Analyzed)
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 23-11A 031833575-0023			Description 78 1/2 -1ST FLOOR - KITCHEN - BEHIND WALL LINOLEUM - MASTIC (DARK BROWN)		
			Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Brown		100.00% Other	None Detected

Initial report from: 12/19/2018 06:08:10



EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018
Tel/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com / manhattanlab@emsl.com>

EMSL Order: 031833575
Customer ID: AZCC25
Customer PO:
Project ID:

Test Report:Asbestos Analysis of Bulk Material

Test	Analyzed Date	Color	Non-Asbestos		Asbestos
			Fibrous	Non-Fibrous	
Sample ID 24-11B 031833575-0024			Description 78 1/2 -1ST FLOOR - KITCHEN - BEHIND WALL LINOLEUM - MASTIC (DARK BROWN)		
			Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Brown		100.00% Other	None Detected
Sample ID 25-11C 031833575-0025			Description 78 1/2 -1ST FLOOR - KITCHEN - WALL - LINOLEUM (WHITE)		
			Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Brown/ White		100.00% Other	None Detected
Sample ID 26-11D 031833575-0026			Description 78 1/2 -1ST FLOOR - KITCHEN - WALL - LINOLEUM (WHITE)		
			Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Brown/ White		100.00% Other	None Detected
Sample ID 27-12A 031833575-0027			Description 78 1/2 -1ST FLOOR - 1ST FLOOR - HALL - FLOOR - FELT PAPER		
			Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Black		100.00% Other	None Detected
Sample ID 28-12B 031833575-0028			Description 78 1/2 -1ST FLOOR - 1ST FLOOR - HALL - FLOOR - FELT PAPER		
			Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Black	None	100.00% Other	<1.00% Chrysotile
Sample ID 39-13A 031833575-0029			Description 76 - 1ST FLOOR - BEDROOM BEHIND BATHROOM - CARPET - MASTIC (TAN)		
			Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Tan		100.00% Other	None Detected

Initial report from: 12/19/2018 06:08:10



EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018
Tel/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order: 031833575
Customer ID: AZCC25
Customer PO:
Project ID:

Test Report:Asbestos Analysis of Bulk Material

Test	Analyzed Date	Color	Non-Asbestos		Asbestos
			Fibrous	Non-Fibrous	
Sample ID 30-13B 031833575-0030			Description 78 - 2ND FLOOR - BEDROOM ADJACENT TO BATHROOM - MASTIC (TAN) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Tan		100.00% Other	None Detected
Sample ID 31-14A 031833575-0031			Description 78 1/2 FLOOR - BEDROOM BEHIND LIVING ROOM - MASTIC (TAN) - FLOOR TILE Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Tan		100.00% Other	None Detected
Sample ID 32-14B 031833575-0032			Description 78 1/2 FLOOR - BEDROOM BEHIND LIVING ROOM - MASTIC (TAN) - FLOOR TILE Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Tan		100.00% Other	None Detected
Sample ID 33-14C 031833575-0033			Description 78 1/2 FLOOR - BEDROOM BEHIND LIVING ROOM - 12"X12" VCT (WHITE) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	White		100.00% Other	None Detected
Sample ID 34-14D 031833575-0034			Description 78 1/2 FLOOR - BEDROOM BEHIND LIVING ROOM - 12"X12" VCT (WHITE) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	White		100.00% Other	None Detected
Sample ID 35-15A 031833575-0035			Description 76 - 1ST FLOOR - BATHROOM - SHOWER - MASTIC (TAN) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Tan		100.00% Other	None Detected

Initial report from: 12/19/2018 06:08:10



EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018
Tel/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order: 031833575
Customer ID: AZCC25
Customer PO:
Project ID:

Test Report:Asbestos Analysis of Bulk Material

Test	Analyzed Date	Color	Non-Asbestos		Asbestos
			Fibrous	Non-Fibrous	
Sample ID 36-15B 031833575-0036			Description 78 1/2 - 1ST FLOOR - BATHROOM - SHOWER - MASTIC (TAN) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Tan		100.00% Other	None Detected
Sample ID 37-16A 031833575-0037			Description 78 1/2 - 1ST FLOOR - BATHROOM - WALL PANEL - MASTIC (LIGHT BROWN) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Brown	None	100.00% Other	<1.00% Chrysotile
Sample ID 38-16B 031833575-0038			Description 78 1/2 - 1ST FLOOR - BATHROOM - WALL PANEL - MASTIC (LIGHT BROWN) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Brown	None	100.00% Other	<1.00% Chrysotile
Sample ID 39-17A 031833575-0039			Description 78 1/2 - 1ST FLOOR - BATHROOM - WALL TILE - MASTIC (TAN) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Tan	5.90% Fibrous (other)	94.10% Other	None Detected
Sample ID 40-17B 031833575-0040			Description 78 1/2 - 1ST FLOOR - BATHROOM - WALL TILE - MASTIC (TAN) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Tan	<1.00% Fibrous (other)	100.00% Other	None Detected
Sample ID 41-18A 031833575-0041			Description 78 1/2 - 1ST FLOOR - BATHROOM - FLOOR - LINOLEUM (WOOD GRAIN) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Brown		100.00% Other	None Detected

Initial report from: 12/19/2018 06:08:10



EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018
Tel/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order: 031833575
Customer ID: AZCC25
Customer PO:
Project ID:

Test Report:Asbestos Analysis of Bulk Material

Test	Analyzed Date	Color	Non-Asbestos		Asbestos
			Fibrous	Non-Fibrous	
Sample ID 42-18B 031833575-0042			Description 78 1/2 - 1ST FLOOR - BATHROOM - FLOOR - LINOLEUM (WOOD GRAIN) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Brown		100.00% Other	None Detected
Sample ID 43-19A 031833575-0043			Description 78 1/2 - 1ST FLOOR - BATHROOM - SINK - MASTIC (GRAY) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Gray		100.00% Other	None Detected
Sample ID 44-19B 031833575-0044			Description 78 1/2 - 1ST FLOOR - BATHROOM - SINK - MASTIC (GRAY) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Gray		100.00% Other	None Detected
Sample ID 45-20A 031833575-0045			Description 78 2ND FLOOR - ADJACENT TO KITCHEN - CEILING - 2'X4' ACOUSTICAL CEILING TILE (PINHOLE FISSURE) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Gray/ White		100.00% Other	None Detected
Sample ID 46-20B 031833575-0046			Description 76 1/2 - 2ND FLOOR - KITCHEN - CEILING - 2'X4' ACOUSTICAL CEILING TILE (PINHOLE FISSURE) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	Gray/ White		100.00% Other	None Detected
Sample ID 47-21A-Skim Coat 031833575-0047			Description 76 1/2 - 2ND FLOOR - BEDROOM BEHIND LIVING ROOM - PLASTER Homogeneity Homogeneous		
PLM NYS 198.1 Friable	12/19/2018	Gray		40.00% Ca Carbonate 60.00% Non-fibrous (other)	None Detected
Inseparable paint / coating layer included in analysis					
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial report from: 12/19/2018 06:08:10



EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018
Tel/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order: 031833575
Customer ID: AZCC25
Customer PO:
Project ID:

Test Report:Asbestos Analysis of Bulk Material

Test	Analyzed Date	Color	Non-Asbestos		Asbestos
			Fibrous	Non-Fibrous	
Sample ID 47-21A-Rough Coat 031833575-0047A			Description 76 1/2 - 2ND FLOOR - BEDROOM BEHIND LIVING ROOM - PLASTER Homogeneity Homogeneous		
PLM NYS 198.1 Friable	12/19/2018	Gray	None	50.00% Gypsum 34.50% Non-fibrous (other) 15.00% Quartz	0.50% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 48-21B 031833575-0048			Description 78 - 2ND FLOOR - BEDROOM BEHIND STAIRWAY - PLASTER Homogeneity Homogeneous		
PLM NYS 198.1 Friable	12/19/2018	Tan	3.00% Hair	55.70% Non-fibrous (other) 40.00% Quartz	1.30% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 49-22A 031833575-0049			Description 76 1/2 - 2ND FLOOR - ADJACENT TO KITCHEN - FLOOR - LINOLEUM (OFF-WHITE) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	White		100.00% Other	None Detected
Sample ID 50-22B 031833575-0050			Description 76 1/2 - 2ND FLOOR - ADJACENT TO KITCHEN - FLOOR - LINOLEUM (OFF-WHITE) Homogeneity Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB	12/19/2018	White		100.00% Other	None Detected
Sample ID 51-23A 031833575-0051			Description 78 - 2ND FLOOR - BATHROOM - JOINT COMPOUND Homogeneity Homogeneous		
PLM NYS 198.1 Friable	12/19/2018	White/ Blue	10.00% Cellulose	60.00% Ca Carbonate 30.00% Non-fibrous (other)	None Detected
Inseparable paint / coating layer included in analysis					
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 52-23B 031833575-0052			Description 78 - 2ND FLOOR - BATHROOM - JOINT COMPOUND Homogeneity Heterogeneous		
PLM NYS 198.1 Friable	12/19/2018	Brown/ Blue	80.00% Cellulose	20.00% Non-fibrous (other)	None Detected
Sample is paint on paper only.					
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial report from: 12/19/2018 06:08:10



EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018
Tel/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order: 031833575
Customer ID: AZCC25
Customer PO:
Project ID:

Test Report:Asbestos Analysis of Bulk Material

Test	Analyzed Date	Color	Non-Asbestos		Asbestos
			Fibrous	Non-Fibrous	
Sample ID 53-23C 031833575-0053			Description 78 - 2ND FLOOR - BATHROOM - DRYWALL		
			Homogeneity Homogeneous		
PLM NYS 198.1 Friable	12/19/2018	Gray		10.00% Ca Carbonate 60.00% Gypsum 30.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 54-23D 031833575-0054			Description 78 - 2ND FLOOR - BATHROOM - DRYWALL		
			Homogeneity Homogeneous		
PLM NYS 198.1 Friable	12/19/2018	Gray	4.00% Glass	55.00% Gypsum 41.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 55-24A 031833575-0055			Description 76 1/2 - 2ND FLOOR - STAIRWAY - PLASTER (TEXTURED)		
			Homogeneity Homogeneous		
PLM NYS 198.1 Friable	12/19/2018	Gray	None	60.00% Gypsum 14.25% Non-fibrous (other) 25.00% Quartz	0.75% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 56-24B-Skim Coat 031833575-0056			Description 76 1/2 - 2ND FLOOR - STAIRWAY - PLASTER (TEXTURED)		
			Homogeneity Homogeneous		
PLM NYS 198.1 Friable	12/19/2018	White		45.00% Ca Carbonate 55.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 56-24B-Rough Coat 031833575-0056A			Description 76 1/2 - 2ND FLOOR - STAIRWAY - PLASTER (TEXTURED)		
			Homogeneity Homogeneous		
PLM NYS 198.1 Friable	12/19/2018	Gray	3.00% Hair	55.70% Non-fibrous (other) 40.00% Quartz	1.30% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial report from: 12/19/2018 06:08:10



EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018
Tel/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order: 031833575
Customer ID: AZCC25
Customer PO:
Project ID:

Test Report:Asbestos Analysis of Bulk Material

The samples in this report were submitted to EMSL for analysis by Asbestos Analysis of Bulk Materials via NYS ELAP Approved Methods . The reference number for these samples is the EMSL Order ID above . Please use this reference number when calling about these samples.

Report Comments:

Sample Receipt Date: 12/15/2018
Analysis Completed Date: 12/19/2018

Sample Receipt Time: 1:27 PM
Analysis Completed Time: 12:51 PM

Analyst(s):

Jon Williams PLM NYS 198.1 Friable (7)

Yolanda Chow PLM NYS 198.1 Friable (9)

Muhsin Parson TEM NYS 198.4 NOB (40)

Samples reviewed and approved by:

James Hall, Laboratory Manager
or Other Approved Signatory

NOB = Non Friable Organically Bound N/A = Not Applicable VCM = Vermiculite Containing Material

-In New York State, TEM is currently the only method that can be used to determine if NOB materials can be considered or treated as non -asbestos containing.

All samples examined for the presence of vermiculite when analyzed via NYS 198.1.

-NYS Guidelines for Vermiculite containing samples are available at http://www.wadsworth.org/labcert/elapcert/forms/VermiculiteInterimGuidance_Rev070913.pdf EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations . Interpretation and use of test results are the responsibility of the client. Samples were received in good condition unless otherwise noted.

This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government . This report may contain data that is not covered by the NVLAP accreditation .

Samples analyzed by EMSL Analytical, Inc. New York, NY NYS ELAP 11506

Initial report from: 12/19/2018 06:08:10

A2Z Environmental llc.

P.O. Box 188
 Pulaski, New York 13142
 (315)527-8888

Chain of Custody Form

J 12/19/18

Location: 76-78 Furnace Street, Little Falls

Number: A2Z12122018b

Page: 1 of 3

031833575

Sample #	material sampled	Location	F/NF/NOB	Analysis requested
01-1a	duct wrap	basement	f	plm <i>(S)</i>
02-1b	duct wrap	basement	f	plm
03-2a	insulation vapor barrier (pink)	basement	NOB TL	tem
04-2b	insulation vapor barrier (pink)	basement	NOB	tem
05-3a	insulation vapor barrier (yellow)	basement	NOB	tem
06-3b	insulation vapor barrier (yellow)	basement	NOB	tem
07-4a	12" x 12" self stick tile (black/white)	78 1/2 - 1st floor - front entrance - floor	NOB	tem
08-4b	12" x 12" self stick tile (black/white)	76 - 1st floor - front entrance - floor	NOB	tem
09-5a	12" x 12" self stick tile (white/pink flower)	76 - 1st floor - hall - floor	NOB	tem
10-5b	12" x 12" self stick tile (white/pink flower)	76 - 1st floor - hall - floor	NOB	tem
11-6a	joint compound	78 1/2 - 1st floor - bathroom	f	plm
12-6b	joint compound	76 - 1st floor - bathroom	f	plm
13-6c	drywall	78 1/2 - 1st floor - bathroom	f	plm
14-6d	drywall	76 - 1st floor - hall	f	plm
15-7a	2' x 4' acoustical ceiling tile (smooth)	76 - 1st floor - bathroom - ceiling	nf	tem
16-7b	2' x 4' acoustical ceiling tile (smooth)	76 - 1st floor - bathroom - ceiling	nf	tem
17-8a	caulk	76 - 1st floor - kitchen - interior door trim	NOB	tem
18-8b	caulk	78 1/2 - 1st floor - bathroom - interior door trim	NOB	tem
19-9a	linoleum (white)	76 - 1st floor - bathroom - floor	NOB	tem
20-9b	linoleum (white)	76 - 1st floor - bathroom - floor	NOB	tem

INSULATION LAB
 RECEIVED
 12 DEC 14 PM 1:27

Instructions: 5 day turn around. Stop at first positive >1% for any multi samples (number and letters indicate multi-samples) (examples: 1-1a,2-1b,3-1c). Could you please email copy of results to a2zconstructionofcnyllc@verizon.net.

yc 12/19/18

First number is sample number then multi-sample number and letter

Collected By: KYLE ROBERTS Date: 12-10-2018

Relinquished By: KYLE ROBERTS Date: 12-13-2018

Received by Lab: [Signature] Date: 12/14/18 1:27 PM

[Handwritten signatures and dates]
 12/19/18
 [Signature]

A2Z Environmental llc.
 P.O. Box 188
 Pulaski, New York 13142
 (315)527-8888

J 12/19/18

Chain of Custody Form

Location: 76-78 Furnace Street, Little Falls

Number: A2Z12122018b

Page: 2 of 3

031833575

Sample #	material sampled	Location	F/NF/NOB	Analysis requested
21-10a	plaster	76 - 1st floor - bedroom behind bathroom	f	plm
22-10b	plaster	78 1/2 - 1st floor - living room	f	plm
23-11a	mastic (dark brown)	78 1/2 - 1st floor - kitchen - behind wall linoleum	NOB	tem
24-11b	mastic (dark brown)	78 1/2 - 1st floor - kitchen - behind wall linoleum	NOB	tem
25-11c	linoleum (white)	78 1/2 - 1st floor - kitchen - wall	NOB	tem
26-11d	linoleum (white)	78 1/2 - 1st floor - kitchen - wall	NOB	tem
27-12a	felt paper	78 1/2 - 1st floor - hall - floor	NOB	tem
28-12b	felt paper	78 1/2 - 1st floor - hall - floor	NOB	tem
29-13a	mastic (tan)	76 - 1st floor - bedroom behind bathroom - carpet	NOB	tem
30-13b	mastic (tan)	78 - 2nd floor - bedroom adjacent to bathroom	NOB	tem
31-14a	mastic (tan) - floor tile	78 1/2 - 1st floor - bedroom behind living room	NOB	tem
32-14b	mastic (tan) - floor tile	78 1/2 - 1st floor - bedroom behind living room	NOB	tem
33-14c	12" x 12" VCT (white)	78 1/2 - 1st floor - bedroom behind living room	NOB	tem
34-14d	12" x 12" VCT (white)	78 1/2 - 1st floor - bedroom behind living room	NOB	tem
35-15a	mastic (tan)	76 - 1st floor - bathroom - shower	NOB	tem
36-15b	mastic (tan)	78 1/2 - 1st floor - bathroom - shower	NOB	tem
37-16a	mastic (light brown)	78 1/2 - 1st floor - bathroom - wall panel	NOB	tem
38-16b	mastic (light brown)	78 1/2 - 1st floor - bathroom - wall panel	NOB	tem
39-17a	mastic (tan)	78 1/2 - 1st floor - bathroom - wall tile	NOB	tem
40-17b	mastic (tan)	78 1/2 - 1st floor - bathroom - wall tile	NOB	tem

13 DEC 14 PM 1:27
 RECEIVED
 IN LAB

Instructions: 5 day turn around. Stop at first positive >1% for any multi samples (number and letters indicate multi-samples) (examples: 1-1a,2-1b,3-1c). Could you please email copy of results to a2zconstructionofcnllc@verizon.net

yc 12/19/18

First number is sample number then multi-sample number and letter

Collected By: _____ Date: 12-10-2018

Relinquished By: _____ Date: _____

Received by Lab: James A. Hoff Date: 12/14/18 P. J. P. P.

SEE PG. 1
 MALTZ
 12/19/18
 6:00PM

A2Z Environmental llc.
 P.O. Box 188
 Pulaski, New York 13142
 (315)527-8888

Chain of Custody Form

Location: 76-78 Furnace Street, Little Falls

Number: A2Z12122018b

Page: 3 of 3

J. Miller
 031833575

Sample #	material sampled	Location	F/NF/NOB	Analysis requested
41-18a	linoleum (wood grain)	78 1/2 - 1st floor - bathroom - floor	NOB	tem <i>(AP)</i>
42-18b	linoleum (wood grain)	78 1/2 - 1st floor - bathroom - floor	NOB	tem
43-19a	mastic (gray)	78 1/2 - 1st floor - bathroom - sink	NOB	tem
44-19b	mastic (gray)	78 1/2 - 1st floor - bathroom - sink	NOB	tem
45-20a	2' x 4' acoustical ceiling tile (pinhole fissure)	78 - 2nd floor - adjacent to kitchen - ceiling	NOB	tem
46-20b	2' x 4' acoustical ceiling tile (pinhole fissure)	76 1/2 - 2nd floor - kitchen - ceiling	NOB	tem
47-21a	plaster	76 1/2 - 2nd floor - bedroom behind living room	f	plm
48-21b	plaster	78 - 2nd floor - bedroom behind stairway	f	plm
49-22a	linoleum (off-white)	76 1/2 - 2nd floor - adjacent to kitchen - floor	NOB	tem
50-22b	linoleum (off-white)	76 1/2 - 2nd floor - adjacent to kitchen - floor	NOB	tem
51-23a	joint compound	78 - 2nd floor - bathroom	f	plm
52-23b	joint compound	78 - 2nd floor - bathroom	f	plm
53-23c	drywall	78 - 2nd floor - bathroom	f	plm
54-23d	drywall	78 - 2nd floor - bathroom	f	plm
55-24a	plaster (textured)	76 1/2 - 2nd floor - stairway	f	plm
56-24b	plaster (textured)	76 1/2 - 2nd floor - stairway	f	plm

13 DEC 14 PM 1:27
 EISL MANHATTAN LAB
 RECEIVED

Instructions: 5 day turn around. Stop at first positive >1% for any multi-samples (number and letters indicate multi-samples) (examples: 1-1a,2-1b,3-1c). Could you please email copy of results to a2zconstructionofcnyllc@verizon.net.

First number is sample number then multi-sample number and letter

Collected By: _____ Date: 12-10-2018

Relinquished By: _____ Date: _____

Received by Lab: *Jean Miller* Date: 12/14/2018

SEE P. 1

yc 12/19/18
MLR
12/19/18
6:20

A2Z Environmental LLC

Asbestos License #73261---Asbestos Certification # 92-09664

P.O. Box 188
Pulaski, New York 13142
(315)527-8888

Appendix D

Laboratory License and Certificate

NEW YORK STATE DEPARTMENT OF HEALTH
WADSWORTH CENTER



Expires 12:01 AM April 01, 2019
Issued April 01, 2018

CERTIFICATE OF APPROVAL FOR LABORATORY SERVICE

Issued in accordance with and pursuant to section 502 Public Health Law of New York State

MR. JAMES HALL
EMSL ANALYTICAL, INC
307 WEST 38TH STREET SUITE 901
NEW YORK, NY 10018

NY Lab Id No: 11506

*is hereby APPROVED as an Environmental Laboratory for the category
ENVIRONMENTAL ANALYSES SOLID AND HAZARDOUS WASTE
All approved subcategories and/or analytes are listed below:*

Miscellaneous

Asbestos in Friable Material	Item 198.1 of Manual EPA 600/M4/82/020
Asbestos in Non-Friable Material-PLM	Item 198.6 of Manual (NOB by PLM)
Asbestos in Non-Friable Material-TEM	Item 198.4 of Manual
Asbestos-Vermiculite-Containing Material	Item 198.8 of Manual
Lead in Dust Wipes	EPA 7000B
Lead in Paint	EPA 7000B

Sample Preparation Methods

EPA 3051A

Serial No.: 57819

Property of the New York State Department of Health. Certificates are valid only at the address shown, must be conspicuously posted, and are printed on secure paper. Continued accreditation depends on successful ongoing participation in the Program. Consumers are urged to call (516) 485-5570 to verify the laboratory's accreditation status.